OMB Control No.: 2127-0004

Part 573 Safety Recall Report

20E-048

Manufacturer Name: Curt Manufacturing LLC

Submission Date: JUL 13, 2020 NHTSA Recall No.: 20E-048 Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Curt Manufacturing LLC

Address: 6208 Industrial Drive

Eau Claire WI 54701

Company phone: 1-800-738-7213

Population:

Number of potentially involved: 447 Estimated percentage with defect: 100 %

Equipment Information:

Brand / Trade 1: CURT

Model: CURT Rambler RV Towbar

Part No.: 70001 Size: N/A

Function: Vehicle Towbar

Descriptive Information: Towbar used to flat tow a vehicle Production Dates: MAR 09, 2020 - APR 14, 2020

Description of Defect:

Description of the Defect: Potential loosening of axial pivot pin

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Axial pivot pin may loosen or potentially fail resulting in separation of the

hitch and activation of secondary safety features.

Description of the Cause : Insufficient retention of axial pivot pin Identification of Any Warning Axial pivot pin connection will be loose

that can Occur:

Involved Components:

Component Name: Towbar axial pivot pin

Component Description: axial pivot pin

Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

06/18/2020 - Received customer notification of loose axial pivot pin

07/07/2020 - Completed analysis

Description of Remedy:

Description of Remedy Program: Replacement of product at no cost to customers

How Remedy Component Differs All replacement product is marked

from Recalled Component:

Identify How/When Recall Condition 06/29/2020 - revised engineering design approved and implemented.

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Will follow the recall schedule listed

Planned Dealer Notification Date : JUL 13, 2020 - JUL 27, 2020 Planned Owner Notification Date : JUL 27, 2020 - AUG 21, 2020

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Part 573 Safety Recall Report

20E-048

Page 3

Name: NR

Address: NR

NR

Country: NR

Company Phone: NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573