**REPORT NUMBER: SINCAP-CAL-21-004** 

# NEW CAR ASSESSMENT PROGRAM (NCAP) MOVING DEFORMABLE BARRIER SIDE IMPACT TEST

Mercedes-Benz AG Stuttgart 2021 Mercedes C300 Four Door Sedan

NHTSA No: M20214301

PREPARED BY: CALSPAN CORPORATION P.O. BOX 400 BUFFALO, NEW YORK 14225



May 10, 2021

**FINAL REPORT** 

PREPARED FOR:
U.S. DEPARTMENT OF TRANSPORTATION
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION
OFFICE OF CRASHWORTHINESS STANDARDS
MAIL CODE: NRM-110
1200 NEW JERSEY AVE SE, ROOM W43-410
WASHINGTON, D.C. 20590

This final test report was prepared for the U.S. Department of Transportation, National Highway Traffic Administration, in response to Contract Number DTNH22-14-D-00352.

This publication is distributed by the U.S. Department of Transportation, National Highway Traffic Safety Administration, in the interest of information exchange. The opinions, findings and conclusions expressed in this publication are those of the author(s) and not necessarily those of the Department of Transportation or the National Highway Traffic Safety Administration. The United States Government assumes no liability for its contents or use thereof.

If trade or manufacturers' names or products are mentioned it is only because they are considered essential to the object of the publication and should not be construed as an endorsement. The United States Government does not endorse products or manufacturers.

Prepared by:	Matthew Pronto	Date:	May 10, 2021
	Matthew Pronko, Test Engineer		
Approved by:	Vanessa Hansen, Operations Program Manager	Date:	May 10, 2021
FINAL REPOR	RT ACCEPTANCE BY OCWS:		
	New Car Assessment Program of Crashworthiness Standards	_	
Date:			
		_	
	ar Assessment Program of Crashworthiness Standards		
Date:			

#### **TECHNICAL REPORT DOCUMENTATION PAGE**

1. Report No.	2. Government Accession No.	3. Recipient's Catalog No.
SINCAP-CAL-21-004		
4. Title and Subtitle		5. Report Date
Final Report of New Car Ass		May 10, 2021
Side Impact MDB Testing of	a	6. Performing Organization Code
2021 Mercedes C300 four d	oor sedan	CAL
NHTSA No.: M20214301		
Matthew Pronko, Test Engin	eer	8. Performing Organization Report No.
Vanessa Hansen, Operation	s Program Manager	CAL-DOT-2021-004
9. Performing Organization Nat	me and Address	10. Work Unit No.
Calspan Corporation		
Transportation Test Operation	ons	11. Contract or Grant No.
P.O. Box 400		DTNH22-14-D-00352
Buffalo, New York 14225		
12. Sponsoring Agency Name a		13. Type of Report and Period Covered:
U.S. Department of Transportation		Final Test Report
National Highway Traffic Safety Administration		February 5, 2021 - May 10, 2021
Office of Crashworthiness Standards (NRM-110)		14. Sponsoring Agency Code
1200 New Jersey Ave., SE,	Room W43-410	NRM-110
Washington, D.C. 20590		

#### 15. Supplementary Notes

#### 16. Abstract

A 55/28, (61.90kph / 38.5 mph), 90<sup>0</sup> Moving Deformable Barrier NCAP Side Impact Test was conducted on the subject 2021 Mercedes C300 four door sedan in accordance with the specifications of the Office of Crashworthiness Standards Test Procedure for the generation of consumer information on vehicle side crash protection. This test was conducted at Calspan Corporation's Transportation Test Operations facility in Buffalo, New York on February 5, 2021.

The impact velocity of the Moving Deformable Barrier (MDB) was 61.97 km/h, and the ambient temperature at the struck (driver's) side of the target vehicle at the time of impact was 21°C. The target vehicle's maximum post-test static crush was 155 mm located at level 3. The test vehicle's occupant performance data is as follows:

Macourement Description		Driver ATD (ES-2re)			
Measurement Description	Units	IARV	Result		
Head Injury Criteria (HIC <sub>36</sub> )	N/A	1000	164.553		
Maximum Thoracic Rib Deflection	mm	44	27.571		
Total Abdominal Force	N	2500	677.569		
Pubic Symphysis Force	N	6000	1351.491		

Measurement Description		Passenger ATD (SID-IIs)			
Measurement Description	Units	IARV	Result		
Head Injury Criteria (HIC <sub>36</sub> )	N/A	1000	212.301		
Lower Spine Resultant Acceleration	G	82	47.659		
Total Pelvic Force (sum of acetabular and iliac forces)	N	5525	3725.516		
Maximum Thoracic Rib Deflection	mm	38*	19.580		
Maximum Abdominal Rib Deflection	mm	45*	13.407		

<sup>\*</sup> Proposed IARV

The two doors on the struck side of the vehicle did not separate from the body at the hinges or latches and the opposite doors did not open during the side impact event.

17. Key Words

18. Distribution Statement

New Car Assessment Program (NCAP) Side Impact MDB ES-2re SID-IIs	Copies of this report are ava National Highway Traffi Technical Information S 1200 New Jersey Ave. Washington, D.C. 2059	c Safety Administration Services Division, SE	
19. Security Class. (of this report)  UNCLASSIFIED	20. Security Class. (of this page) UNCLASSIFIED	21. No. of Pages	22. Price

# **TABLE OF CONTENTS**

<u>Section</u>		<u>Page</u>
1	Test Purpose and Procedure	1-1
2	Summary of Test Results	2-1
3	Occupant and Vehicle Information	3-1
Data Sheet		<u>Page</u>
1	General Test and Vehicle Parameter Data	3-2
2	Seat, Seat Belt, Steering Wheel Adjustment and Fuel System Data	3-6
3	Dummy Longitudinal Clearance Dimensions	3-10
4	Dummy Lateral Clearance Dimensions	3-11
5	Camera and Instrumentation Data	3-12
6	Test Vehicle Accelerometer Locations	3-13
7	MDB Accelerometer Locations	3-14
8	Post-Test Observations	3-15
9	MDB Summary of Results	3-17
10	Test Vehicle Profile Measurements	3-18
11	Test Vehicle Exterior Crush Measurements	3-19
12	MDB Exterior Static Crush Measurements	3-22
13	Vehicle and MDB Damage Profile Distances	3-23
14	FMVSS No. 301 Static Rollover Results	3-24
15	Dummy/Vehicle Temperature and Humidity Stabilization Data	3-25
<u>Appendix</u>		<u>Page</u>
Α	Photographs	A-1
В	Vehicle and Dummy Response Data Plots	B-1
С	Dummy Configuration and Performance Verification Data	C-1
D	Test Equipment and Instrumentation Calibration Data	D-1

# **SECTION 1**

# **TEST PURPOSE AND PROCEDURE**

This moving deformable barrier side impact test is part of the MY 2021 New Car Assessment Program Side Impact Test Program, sponsored by the National Highway Traffic Safety Administration (NHTSA), under contract number DTNH22-14-D-00352. The purpose of this test is to generate comparative side impact performance in a 2021 Mercedes C300 four door sedan. The side impact test was conducted in accordance with the Office of Crashworthiness Standard's Laboratory Test Procedure dated March 2020.

#### **SECTION 2**

#### **SUMMARY OF TEST RESULTS**

A 2021 Mercedes C300 four door sedan was impacted on the left (driver's) side by a Moving Deformable Barrier (MDB) which was moving forward in a 27° crabbed position to the tow road guidance system at a velocity of 61.97 km/h. The target vehicle was stationary and was positioned at an angle of 63° to the line of forward motion. The side impact test was conducted by the Calspan Corporation's Transportation Test Operations Center in Buffalo, New York on February 5, 2021. Pre-test and post-test photographs of the test vehicle, the MDB and the dummies (ES-2re and SID-IIs) are included in this report.

Dummies were placed in the driver and left rear designated seating positions according to instructions specified in the OCWS Side Impact Laboratory Test Procedure, dated March 2020. The side impact event was documented by 9 high-speed and 2 real-time cameras. Camera locations are included in this report.

The Dummies were instrumented in the following manner:

DRIVER ATD (ES-2re)

Primary and redundant head CG tri-axial accelerometers

Chest upper rib, middle rib, and lower rib y-axis displacement potentiometers

Abdomen forward, middle, and rear y-axis load cells

Lower spine (T12) tri-axial accelerometers

Public symphysis y-axis load cell

PASSENGER ATD (SID-IIs)

Primary and redundant head CG tri-axial accelerometers

Chest upper rib, middle rib, and lower rib y-axis displacement potentiometers

Abdomen upper rib and lower rib y-axis displacement potentiometers

Lower spine (T12) tri-axial accelerometers

Acetabulum and iliac wing y-axis load cells

Appendix B contains the vehicle and dummy response data. Dummy configuration and performance verification data can be found in APPENDIX C of this report. Appendix D of this report contains the test equipment and instrumentation calibration data.

# **DUMMY INJURY VALUES**

Measurement Description	Driver ATD (ES-2re)		
Measurement Description	Units	Threshold	Result
Head Injury Criteria (HIC36)		1000	164.553
Maximum Thorax Rib Deflection	mm	44	27.571
Combined Abdominal Force	N	2500	677.569
Pubic Symphysis Force	N	6000	1351.491

Measurement Description	Passenger ATD (SID-IIs)		
Measurement Description	Units	Threshold	Result
Head Injury Criteria (HIC36)		1000	212.301
Lower Spine (T12) Resultant Acceleration	G	82	47.659
Total Pelvic Force (sum of acetabular and iliac forces)	N	5525	3725.516
Maximum Thoracic Rib Deflection	mm	38*	19.580
Maximum Abdominal Rib Deflection	mm	45*	13.407

<sup>\*</sup>Proposed IARV

#### SUPPLEMENTAL RESTRAINT INFORMATION

Restraint Type	Left Front (Driver) Occupant Location 1		Left Rear (Passenger) Occupant Location 4	
	Mounted	Deployed	Mounted	Deployed
Frontal Air bag	Yes	No		
Knee Air bag	Yes	No		
Side Air bag 1 - Curtain	Yes	Yes	Yes	Yes
Side Air bag 2 – Torso/Pelvis Air bag	Yes	Yes	No	N/A
Side Air bag 3 – Torso Air bag	No	N/A	Yes	Yes
Seat Belt Pretensioner	Yes	Yes	Yes	No
Seat Belt Load Limiter	Yes	Yes	Yes	No
Other				

# **GENERAL COMMENTS:**

- 1. P1 serial number F034
- 2. P4 serial number 300

# **Data Anomalies:**

The following channel was questionable for

- Left Lower A-Pillar Y, Exceeded calibration range at 4.7 ms
- Left Lower B-Pillar Y, Exceeded calibration range and saturated at 8.7 ms
- Left Mid B-Pillar Y, Exceeded calibration range and saturated at 9.2 ms

#### **SECTION 3**

# **OCCUPANT AND VEHICLE INFORMATION**

This section contains information reporting for the following Data Sheets:

Data Sheet No. 1 - General Test and Vehicle Parameter Data

Data Sheet No. 2 - Seat, Seat Belt, Steering Wheel Adjustment and Fuel System Data

Data Sheet No. 3 – Dummy Longitudinal Clearance Dimensions

Data Sheet No. 4 – Dummy Lateral Clearance Dimensions

Data Sheet No. 5 – Camera and Instrumentation Data

Data Sheet No. 6 – Test Vehicle Accelerometer Locations

Data Sheet No. 7 – MDB Accelerometer Locations

Data Sheet No. 8 – Post-Test Observations

Data Sheet No. 9 – MDB Summary of Results

Data Sheet No. 10 – Test Vehicle Profile Measurements

Data Sheet No. 11 – Test Vehicle Exterior Crush Measurements

Data Sheet No. 12 – MDB Exterior Static Crush Measurements

Data Sheet No. 13 – Vehicle and MDB Damage Profile Distances

Data Sheet No. 14 - FMVSS No. 301 Static Rollover Results

Data Sheet No. 15 – Dummy/Vehicle Temperature and Humidity Stabilization Data

# DATA SHEET NO. 1 GENERAL TEST AND VEHICLE PARAMETER DATA

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021

# **TEST VEHICLE INFORMATION AND OPTIONS**

	TEST VEHICLE INFORMA
NHTSA No.	M20214301
Model Year	2021
Make	Mercedes
Model	C300
Body Style	Four Door Sedan
VIN	W1KWF8DB0MR613651
Body Color	Silver
Odometer Reading (km/mi)	7 Miles
Engine Displacement (L)	2.0
Type/No. Cylinders	14
Engine Placement	Inline
Transmission Type	Automatic
Transmission Speeds	9-Speed
Overdrive	Yes
Final Drive	Rear Wheel Drive
Roof Rack	No
Sunroof/T-Top	Yes
Running Boards	No
Tilt Steering Wheel	Yes
Power Seats	Yes
Anti-Lock Brakes (ABS)	Yes

Traction Control System (TCS)	Yes
Auto-Leveling System	No
Automatic Door Locks (ADL)	Yes
Power Window Auto-Reverse	No
Other Optional Feature	N/A
Driver Front Air bag	Yes
Driver Curtain Air bag	Yes
Driver Head/Torso Air bag	No
Driver Torso Air bag	No
Driver Torso/Pelvis Air bag	Yes
Driver Pelvis Air bag	No
Driver Knee Air bag	Yes
Rear Pass. Curtain Air bag	Yes
Rear Pass. Head/Torso Air bag	No
Rear Pass. Torso Air bag	Yes
Rear Pass. Torso/Pelvis Air bag	No
Rear Pass. Pelvis Air bag	No
Driver Seat Belt Pretensioners	Yes
Rear Pass. Seat Belt Pretensioners	Yes
Driver Load Limiter	Yes
Rear Pass. Load Limiter	Yes
Other Safety Restraint	N/A

Does owner's manual provide instructions to turn off automatic door locks?

Yes

# **DATA FROM CERTIFICATION LABEL**

Manufactured By	Mercedes-Benz AG Stuttgart
Date of Manufacture	10/20
Vehicle Type	Passenger Car

GVWR (kg)	2090
GAWR Front (kg)	1010
GAWR Rear (kg)	1100

# **VEHICLE SEATING AND WEIGHT CAPACITY DATA**

Measured Parameter	Front	Rear	Third	Total	
Designated Seating Capacity (DSC)	2	3	N/A	5	
Capacity Weight (VCW) (kg)				444	(A)
DSC X 68.04 kg				340.2	(B)
Cargo Weight (RCLW) (kg)				103.8	(A-B)

# **VEHICLE SEAT TYPE**


		Туре с	of Seat Pa	n	Type of Seat Back			
Seating Location		Bucket Banch Split		Elmand.	Adjustable			
	Bucket	Bench	Bench	Contoured	Fixed	W/ Lever	W/ Knob	
Front Seat	Χ						X	
Rear or Second Row Seat			Х		Х			
Third Row seat								

# DATA SHEET NO. 1 ... (CONTINUED) GENERAL TEST AND VEHICLE PARAMETER DATA

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021

# **VEHICLE TIRE INFORMATION**

Collected for year, make, model, & VIN, all items circled in red, tire manufacturer and tire name.



# TIRE SIDEWALL INFORMATION

Measured Parameter	Front	Rear
Maximum Tire Pressure (kPa)	350	350
Cold Pressure (kPa)	280	320
Recommended Tire Size	225/50R17	225/50R17
Tire Size on Vehicle	225/50R17	225/50R17
Tire Manufacturer	Continental	Continental
Tire Model	ContiproContact SSR	ContiproContact SSR
Treadwear	400	400
Traction	AA	AA
Temperature Grade	A	A
Tire Plies Sidewall	2 Rayon	2 Rayon
Tire Plies Body	1 Rayon, 2 Steel,	1 Rayon, 2 Steel,
The Files Body	1 Polyamide	1 Polyamide
Load Index/Speed Symbol	94H	94H
Tire Material	Rubber	Rubber
DOT Safety Code Left	LM40WB932920	LM40WB932920
DOT Safety Code Right	LM40WB932920	LM40WB932920

# DATA SHEET NO. 1 ... (CONTINUED) GENERAL TEST AND VEHICLE PARAMETER DATA

Test Vehicle:2021 Mercedes C300 four door sedanNHTSA No.:M20214301Test Program:NCAP Side MDB Impact TestTest Date:2/5/2021

#### **TIRE PRESSURES**

	Units	LF	RF	LR	RR
As Delivered	kPa	240	242	290	298
Tire Placard	kPa	280	280	320	320
Owner's Manual	kPa	280	280	320	320
As Tested	kPa	280	280	320	320

### **MDB TIRE SPECIFICATIONS**

	Units	Requirement	LF	RF	LR	RR
Tire Size		P205/75R15	P205/75R15	P205/75R15	P205/75R15	P205/75R15
Tire Pressure	kPa	200 ± 21	207	207	207	207

# **TEST VEHICLE WEIGHTS**

	Units	As Delivered (UVW)			As Tested (ATW)			Fı	ully Loade	ed
	Uiils	Front	Rear	Total	Front	Rear	Total	Front	Rear	Total
Left	kg	417	374		468	455		452	485	
Right	kg	426	370		465	422		429	453	
Ratio	%	53.0	47.0		52	48		48.0	52.0	
Totals	kg	843	744	1587	933	877	1810	881	938	1819

# TARGET TEST WEIGHT CALCULATION

Measured Parameter	Units	Value	
Total Delivered Weight (UVW)	kg	1587	(A)
Sum of Actual Weight of 1 ES2re and 1 P572 ATD (SID-IIs)	kg	127	(B)
Rated Cargo / Luggage Weight (RCLW)	kg	103.8	(C)
Calculated Target Vehicle Test Weight (TVTW)	kg	1817.8	(A+B+C)

Does the measured As Test Vehicle Weight lie within the required weight range

(i.e. Calculated Test Vehicle Target Weight – 4.5 kg to – 9 kg)?	Χ	Yes		No
--	---	-----	--	----

# **TEST VEHICLE ATTITUDES AND CG**

Measurement Description	Units	Fully Loaded	As Tested	Meets Requirement**
LF	mm	696	688	Yes
RF	mm	700	690	Yes
RR	mm	699	689	Yes
LR	mm	694	687	Yes
Vehicle CG (Aft of Front Axle)	mm	1463	1375	
Vehicle CG (Left(+)/Right(-) from Longitudinal Centerline)	mm	23	16	

<sup>\*\*\*</sup> The "As Tested" vehicle attitude measurements must be equal to or within ± 10mm of the "Fully Loaded" vehicle attitude measurements at each wheel well. Indicate "Yes" or "No" for "Meets Requirements".

Test height adjustable suspension setting, if applicable:	N/A	
---	-----	--

# DATA SHEET NO. 1 ... (CONTINUED) GENERAL TEST AND VEHICLE PARAMETER DATA

Test Vehicle:2021 Mercedes C300 four door sedanNHTSA No.:M20214301Test Program:NCAP Side MDB Impact TestTest Date:2/5/2021

# WEIGHT OF BALLAST AND VEHICLE COMPONENTS REMOVED TO MEET TVTW

Component Description	Weight (kg)
Trunk Carpeting	6
Tail Light	1
Ballast / Equipment Added	39.3

# **TEST SURFACE MARKINGS**

	Distance from 63° Impact Angle Line (mm)		
Fore 25 mm target	890		
Aft 25 mm target	890		
Pre-Impact Angle Line	236		

Parallel Track Target	X Location (mm)	Y Location (mm)
Α	0	0
В	2955	1555
С	2955	3555
D	0	3000

# DATA SHEET NO. 2 SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT AND FUEL SYSTEM DATA

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021

#### **SEAT POSITIONING**

The driver's seat, front center seat (if applicable), and right front passenger's seat should be set to the mid-track, lowest, mid-angle position. The struck-side rear passenger's seat, rear center seat, and non-struck side rear passengers' seats should be set to the rear-most, lowest, mid-angle position.

# **SCRL ANGLE RANGE**

Seat	SCRL (°)			
Seat	Max	Min	Mid	
Driver Seat	19.4	11.7	15.6	
Front Passenger Seat	21.6	12.1	16.9	
Front Center Seat*	-			
Struck Side Rear Seat	Fixed	Fixed	Fixed	
Non-Struck Side Rear Seat	Fixed	Fixed	Fixed	
Rear Center Seat*	Fixed	Fixed	Fixed	

<sup>\*</sup>if applicable

#### **SEAT HEIGHT AND ANGLE**

	As Tested	As Tested	SCRP	SC	RP Height (m	m)
Seat	SCRL Angle (Mid) (°)	SCRP Height (mm)	Height Position	Rearmost	Mid- Fore/Aft	Forward- Most
			Max	65	81	79
Driver Seat	15.6	14	Mid	32	47	54
			Min	0	14	28
Front			Max	75	90	103
Passenger	16.9	15	Mid	38	52	67
Seat			Min	0	15	30
Front			Max	-	-	-
Center	N/A	N/A	Mid	-	-	-
Seat*			Min	-	-	-
Struck Side			Max	-	-	-
Rear Seat	Fixed	Fixed	Mid	-	-	-
iteai Seat			Min	-	-	-
Non-Struck			Max	-	-	-
Side Rear	Fixed	Fixed	Mid	-	-	-
Seat			Min	-	-	-
Door Contar			Max	-	-	-
Rear Center Seat*	Fixed	Fixed	Mid	-	-	-
Seal			Min	-	-	-

<sup>\*</sup>if applicable

# DATA SHEET NO. 2 ... (CONTINUED) SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT AND FUEL SYSTEM DATA

Test Vehicle:2021 Mercedes C300 four door sedanNHTSA No.:M20214301Test Program:NCAP Side MDB Impact TestTest Date:2/5/2021


### **SEAT FORE / AFT POSITION**

Seat	Total Fore	/ Aft Travel	Test Position from Forwardmost Position		
	mm Detents*		mm	Detent*	
Driver Seat	257	N/A	129	N/A	
Front Passenger Seat	262	N/A	131	N/A	
Front Center Seat*	-	-	-	-	
Struck Side Rear Seat	Fixed	Fixed	Fixed	Fixed	
Non-Struck Side Rear Seat	Fixed	Fixed	Fixed	Fixed	
Rear Center Seat*	Fixed	Fixed	Fixed	Fixed	

<sup>\*</sup>if applicable

#### **SEAT BACK ANGLE ADJUSTMENT**

The driver's seat back is positioned to the manufacturer's designated design angle. The front center and front passenger's seat backs are positioned in a similar manner as the driver's seat back. The struck side rear seat back is positioned such that the dummy's head is level. The rear center and non-struck side rear outboard seat backs are positioned in a similar manner as the struck-side rear seat back.



FRONT SEAT ASSEMBLY

Seat	Total Seat Ba Rang		Test Position from Most Upright	
	Degrees Detents*		Degrees	Detents*
Driver Seat w/ Seated Dummy	50	Power	9.0	Power
Front Passenger Seat	50	Power	9.0	Power
Front Center Seat*	-	-	-	-
Struck Side Rear Seat w/ Seated Dummy	Fixed	Fixed	Fixed	Fixed
Non-Struck Side Rear Seat	Fixed	Fixed	Fixed	Fixed
Rear Center Seat*	Fixed	Fixed	Fixed	Fixed

<sup>\*</sup>if applicable

# DATA SHEET NO. 2 ... (CONTINUED) SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT AND FUEL SYSTEM DATA

Test Vehicle:2021 Mercedes C300 four door sedanNHTSA No.:M20214301Test Program:NCAP Side MDB Impact TestTest Date:2/5/2021

#### SEAT BELT ANCHORAGE ADJUSTMENT

Seat belt anchorages are adjusted in accordance with the information provided by the manufacturer on Form No. 1. For this test zero is defined as the uppermost position.

	Total # of Positions	Placed in Position #
Driver Seat	5 (0-4)	0
Rear Seat	Fixed	Fixed

#### **HEAD RESTRAINT ADJUSTMENT**


The driver's head restraint is adjusted to the highest and most full forward in-use position. The struck-side rear passenger's head restraint is adjusted to the lowest and most full forward in-use position.

	Total # of Positions	Placed in Position #
Driver Seat	Infinite (Power)	Full Up / Full Forward
Rear Seat	5 (0-4)	Lowermost

#### STEERING COLUMN ADJUSTMENT

Steering wheel and column adjustments are made so that the steering wheel hub is at the center of its geometric locus it describes when it moves through its full range of motion.


	Degrees	Fore/Aft Position (mm)
Lowermost – Position 1	19.2	
Geometric Center – Position 2	21.3	
Uppermost – Position 3	23.4	
Telescoping Steering Wheel Travel		55
Test Position	21.3	28



### **FUEL PUMP**

Describe the fuel pump type, details about how it operates, and the location of the fuel filler neck.

The vehicle is equipped with an electric fuel pump. The fuel filler neck is on the right side of the vehicle. The pump creates positive pressure in the fuel lines, pushing the gasoline to the engine. See form 1 for more information.



VEHICLE FUEL TANK ASSEMBLY

# DATA SHEET NO. 2 ... (CONTINUED) SEAT, SEAT BELT, STEERING WHEEL ADJUSTMENT AND FUEL SYSTEM DATA

Test Vehicle:	2021 Mercedes C300 four door sedan	NHTSA No.:	M20214301	
Test Program:	NCAP Side MDB Impact Test	Test Date:	2/5/2021	


# **FUEL TANK CAPACITY**

	Liters
Usable Capacity of "Standard Tank" (see Form No. 1)	65.9
Usable Capacity of "Optional Tank" (see Form No. 1)	N/A
Usable Capacity of Standard Tank (see Owner's Manual)	65.9
Usable Capacity of Optional Tank (see Owner's Manual)	N/A
93% of Usable Capacity	61.3
Actual Amount of Solvent Used in Test	61.3
1/3 of Usable Capacity	22

Is the Actual Amount of Solvent Used in the test equal to  $93\% \pm 1\%$  of the Usable Capacity stated in Form No. 1? **X** Yes **No** 

# DATA SHEET NO. 3 DUMMY LONGITUDINAL CLEARANCE DIMENSIONS

Test Vehicle:2021 Mercedes C300 four door sedanNHTSA No.:M20214301Test Program:NCAP Side MDB Impact TestTest Date:2/5/2021



# **LEFT SIDE VIEW**


NOTE: 2-DOOR VEHICLE SHOWN. REAR DUMMY PHX & PHZ MEASUREMENTS FOR A 4-DOOR VEHICLE WOULD USE THE C-POST STRIKER AS A REFERENCE POINT

# **DUMMY LONGITUDINAL CLEARANCE DIMENSION INFORMATION**

Driver Code	Pass. Code	Description		ver lo. F034)		senger I No.300)
Driver Code	Pass. Code	Description	Length (mm)	Angle	Length (mm)	Angle
HH		Header to Header	415			
HW		Header to Windshield	675			
HZ	HZ	Head to Roof Liner	172		210	
NR	NB	Nose to Rim/Seat Back	476		440	
CD	СВ	Chest to Dash/Seat Back	577		456	
CS		Chest to Steering Wheel	380			
KD(L)/KDA(L)°	KB(L)/KBA(L)°	Left Knee to Dash/Seat Back	235	27.4	233	4.8
KD(R)/KDA(R)°	KB(R)/KBA(R)°	Right Knee to Dash/Seat Back	220	23.2	228	2.3
PAX°	PAX°	Pelvic Tilt Angle X		22.1		18.2
	PAY°	Pelvic Tilt Angle Y				0.2
PHX	PHX	Hip Point to Striker (X-Axis)	112		123	
PHZ	PHZ	Hip Point to Striker (Z-Axis)	239		215	

# DATA SHEET NO. 4 DUMMY LATERAL CLEARANCE DIMENSIONS

Test Vehicle:2021 Mercedes C300 four door sedanNHTSA No.:M20214301Test Program:NCAP Side MDB Impact TestTest Date:2/5/2021




FRONT VIEW OF DUMMY

# **DUMMY LATERAL CLEARANCE DIMENSION INFORMATION**

Code	Measurement Description	Units Driver (Serial No. F034		Passenger (Serial No. 300)
HR	Head to Side Header	mm	188	232
HS	Head to Side Window	mm	312	380
AD	Arm to Door	mm	92	168
HD	Hip Point to Door	mm	138	180

# DATA SHEET NO. 5 CAMERA AND INSTRUMENTATION DATA

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021



# **CAMERA LOCATIONS AND DATA**

		Co	ordinates (m	Lens	Operating	
No.	Camera View	Х	Y	Z	Length (mm)	Frame Rate (fps)
1	Overhead Overall	-261	0	-8139	12.5	1000
2	Overhead Close-up	0	0	-8139	24	1000
3	Left Impact Point (MDB)			25	1000	
4	Side Overall (MDB)				8	1000
5	Rear	0	7303	-1464	28	1000
6	Left Front	-2362	-6391	-1436	24	1000
7	Driver Front (OB)				25	1000
8	Driver Side (OB)				12.5	1000
9	Passenger Side (OB)				12.5	1000
10	Real-time Left Rear				Zoom	60
11	Real-time In run				Zoom	60

Notes: Reference: Impact Point projected to Ground

+X = To Front of MDB, +Y = To Right of MDB, +Z = Down

If applicable, explain why camera(s) did not operate as intended:

All cameras operated normally


#### **INSTRUMENTATION**

Driver Dummy Channels	16
Passenger Dummy Channels	16
Vehicle Structure Accelerometers	23
MDB Accelerometers	7
Total	62

<sup>\*</sup>All measurements accurate to ± 6 mm.

# DATA SHEET NO. 6 TEST VEHICLE ACCELEROMETER LOCATIONS

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021



# **TEST VEHICLE ACCELEROMETER LOCATIONS**

No.	Accelerometer Location	Coordinates (mm)			
NO.	Acceleroffieter Location	Χ	Υ	Z	
1	Vehicle CG	2006	-2	199	
2	Right Sill at Front Seat	2702	679	256	
3	Right Sill at Rear Seat	1882	679	256	
4	Left Sill at Front Door	2744	-698	309	
5	Left Sill at Rear Door	1865	-696	320	
6	A-Post Lower	3168	-682	49	
7	A-Post Middle	3076	-649	-357	
8	B-Post Lower	2151	-693	18	
9	B-Post Middle	2116	-676	-226	
10	Front Seat Track	2339	-577	332	
11	Rear Seat Structure	1799	-599	310	
12	Rt. Rear Occ. Compartment	2011	380	401	
13	Engine Block	4064	-25	-220	
14	Rear Above Axle	843	-5	107	


Reference: X – Rear surface of vehicle (+ forward)

Y – Vehicle centerline (+ to right)

Z – Ground plane (+ down)

# DATA SHEET NO. 7 MDB ACCELEROMETER LOCATIONS

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021



# MDB ACCELEROMETER LOCATIONS

No.	Accelerometer Location	Coordinates (mm)			
NO.	Accelerometer Location	X	Y	Z	
1	MDB CG	1859	0	-330	
2	MDB Rear	386	-660	-660	

Reference: X – Face of MDB (+ forward)

Y – MDB centerline (+ to right)

Z – Ground plane (+ down)

Width between left and right contact switches (mm):

1475

# DATA SHEET NO. 8 POST-TEST OBSERVATIONS

Test Vehicle:2021 Mercedes C300 four door sedanNHTSA No.:M20214301Test Program:NCAP Side MDB Impact TestTest Date:2/5/2021

# **TEST DUMMY INFORMATION AND CONTACT POINTS**

Dummy Body Part	Front Seat Dummy (ES-2re)	Rear Seat Dummy (SID-IIs)
Face	Curtain Airbag	Curtain Airbag
Top of Head	Curtain Airbag & Side Header	Curtain Airbag
Left Side of Head	Curtain Airbag	Curtain Airbag
Back of Head	Curtain Airbag, Head Rest	Curtain Airbag, Center Headrest
Left Shoulder	Torso/Pelvis Airbag, Driver Door	Torso Airbag, Seatback
Upper Torso	Torso/Pelvis Airbag, Seat Back	Seat Back
Lower Torso	Torso/Pelvis Airbag, Seat Back	Seat Back
Left Hip	Torso/Pelvis Airbag, Driver Door,	Left Rear Passenger Door,
Lett iip	Seatpan	Seat Back, Seatpan
Left Knee	Driver Door	Right Rear Passenger Door

# POST-TEST DOOR PERFORMANCE

	Struck Side		Non-Struck Side		Rear
Description	Front	Rear	Front	Rear	Hatch/ Other
Remained Closed and Operational	No	No	Yes	Yes	Yes
Total Separation from Vehicle at Hinges or Latches	No	No	No	No	No
Latch or Hinge Systems Pulled Out of Their Anchorages	No	No	No	No	No
Disengaged from Latched Position	No	No	No	No	No
Latch Separated from Striker	No	No	No	No	No
Jammed Shut	Yes	Yes	No	No	No
If Door Opened at Striker, Width of Opening at Striker (mm)	0	0	0	0	0

# **POST-TEST SEAT PERFORMANCE**

Description	Struc	k Side	Non-Struck Side	
Description	Front	Rear	Front	Rear
Seat Movement Along Seat Track	No	No	No	No
Seat Disengagement from Floor Pan	No	No	No	No
Seat Back Movement from Initial Position	No	No	No	No
Seat Back Collapse	No	No	No	No

# **POST-TEST STRUCTURAL OBSERVATIONS**

Critical Areas of Performance	Observations and Conclusions
Pillar Performance	B-Pillar & C-Pillar Buckled
Sill Separation	None
Windshield Damage	None
Side Window Damage	Rear Passenger Window Shattered
Other Notable Effects	None

# DATA SHEET NO. 8 ... (CONTINUED) POST-TEST OBSERVATIONS

Test Vehicle:2021 Mercedes C300 four door sedanNHTSA No.:M20214301Test Program:NCAP Side MDB Impact TestTest Date:2/5/2021

# SUPPLEMENTAL RESTRAINT SYSTEM INFORMATION

Restraint Type		k Side iver	Struck Side Rear Passenger	
	Mounted	Deployed	Mounted	Deployed
Frontal Air bag	Yes	No		
Knee Air bag	Yes	No		
Side Air bag 1 - Curtain	Yes	Yes	Yes	Yes
Side Air bag 2 - Torso/Pelvis Air bag	Yes	Yes	No	N/A
Side Air bag 3 – Torso Air bag	No	N/A	Yes	Yes
Seat Belt Pretensioner	Yes	Yes	Yes	No
Seat Belt Load Limiter	Yes	Yes	Yes	No
Other				

# **IMPACT POINT LOCATION DATA**

Measured Parameter	Units	Tolerance	Value
Vehicle Wheel Base	mm		2838
Vertical Impact Reference Line (Aft of Front Axle - Intended Impact Point)	mm		479
Actual Impact Point (Aft of Frontal Axle)	mm		486
Horizontal Offset (+ forward / - rearward)	mm	+/- 50 of Intended Impact Point	-7
Vertical Offset (+ down / - up)	mm	+/- 20 of Intended Impact Point	0

# DATA SHEET NO. 9 MDB SUMMARY OF RESULTS

Test Vehicle:2021 Mercedes C300 four door sedanNHTSA No.:M20214301Test Program:NCAP Side MDB Impact TestTest Date:2/5/2021

# **MDB SPECIFICATIONS**

Measurement Description	Length (mm)
Overall Width of Framework Carriage	1,250
Overall Length Including Honeycomb Frame	4,120
Wheelbase of Framework Carriage	2,600
CG Location of Front Axle	1,120

# **MDB WEIGHTS**

	Units	Front Axle	Rear Axle	Total
Left	kg	392.5	297.5	690.0
Right	kg	386.0	291.5	677.5
Ratio	%	57.4%	42.6%	100.0%
Totals	kg	778.5	589.0	1367.5

# SPEED AND ANGLE AT IMPACT DATA


Measured Parameter	Units	Requirement	Value
Trap No. 1 Velocity (Primary)	km/h	61.10 to 62.70	61.97
Trap No. 2 Velocity (Redundant)	km/h	61.10 to 62.70	61.92
MDB CL to Target Vehicle CL	degrees	88.5 to 91.5	90
MDB Forward Line of Motion to Target Vehicle CL	degrees	62.5 to 63.5	63.0
MDB Crabbed angle to MDB Forward Line of Motion	degrees	26.0 to 28.0	27.0

# MAXIMUM STATIC CRUSH OF HONEYCOMB IMPACT FACE

	Vertical Locat	ion	From Ce	Maximum Crush	
Row	Description	Height (mm)	Distance (mm)	Direction	(mm)
Α	Center of Bumper	432	400	Right	262
В	Top of Bumper	533	400	Right	181
С	Mid-Level	686	800	Left	175
D	Top of Stack	813	800	Left	187

# DATA SHEET NO. 10 TEST VEHICLE PROFILE MEASUREMENTS

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021




LEFT SIDE VIEW
All MEASUREMENTS IN (mm) WITH TOLERANCE OF ± 3mm

# **VEHICLE PRE- AND POST-TEST MEASUREMENT INFORMATION**

Code	Description	Pre-Test	Post-Test	Difference
Α	Wheelbase	2838	2833	-5
В	Front Axle to FSOV	789	799	10
С	Rear Axle to RSOV	1056	1057	1
D	Total Length at Centerline	4684	4689	5
Е	Front Bumper Thickness	254	254	0
F	Front Bumper Bottom to Ground	201	205	4
G	Sill Height at Front Wheel Well	162	172	10
Н	Sill Height at Front Door Leading Edge	160	170	10
I	Sill Height at B Pillar	173	168	-5
J1	Sill Height at Rear Wheel Well	160	161	1
J2	Pinch Weld Height at Rear Wheel Well	164	159	-5
K	Sill Height Aft of Rear Wheel Well	200	205	5
L	Rear Bumper Thickness	250	250	0
М	Rear Bumper Bottom to Ground	363	367	4
N	Sill Height to Window Bottom of Front Window Sill	704	707	3
0	Front Door Leading Edge to Impact CL	613	609	-4
Р	Rear Door Trailing Edge to Impact CL	1481	1437	-44
Q	Front Window Opening	419	408	-11
R	Right Side Length	4578	4579	1
S	Left Side Length	4578	4577	-1
Т	Maximum Vehicle Width	1797	1718	-79
U	Front Wheel Track Width	1561	1560	-1
V	Rear Wheel Track Width	1545	1545	0

# DATA SHEET NO. 11 TEST VEHICLE EXTERIOR CRUSH MEASUREMENTS

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021



# **MAXIMUM EXTERIOR CRUSH MEASUREMENTS**

Level	Measurement Description	Units	Height Above Ground	Maximum Exterior Static Crush	Distance from Impact	
1	Sill Top	mm	257	14	900	
2	Driver Hip Point	mm	507	122	1650	
3	Mid-Door	mm	646	155	900	
4	Window Sill	mm	926	130	1650	
5	Window Top	mm	1389	4	1350	

<sup>\*</sup>window top level bent outward from original position

**NOTE:** The above measurements should be taken along the vertical impact reference line. Vehicle measurements forward of the vertical impact reference line are negative.

# DATA SHEET NO. 11 ... (CONTINUED) TEST VEHICLE EXTERIOR CRUSH MEASUREMENTS

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021


# **EXTERIOR CRUSH MEASUREMENTS AT EACH LEVEL**

		F	Pre-Tes	it			Р	ost-Tes	t			[	Differen	се	
	1	2	3	4	5	1	2	3	4	5	1	2	3	4	5
-900															
-750															
-600															
-450															
-300															
-150			908					921					-13		
0	867	898	898			868	915	904			-1	-17	-6		
150	861	891	899	786		861	843	878	778		0	48	21	8	
300	863	893	902	805		859	805	827	806		4	88	75	-1	
450	863	894	904	819		857	804	791	799		6	90	113	20	
600	864	895	906	830		853	792	777	801		11	103	129	29	
750	860	896	907	839		848	790	759	799		12	106	148	40	
900	859	896	908	848	587	845	787	753	802	586	14	109	155	46	1
1050	857	895	907	852	587	843	785	771	802	585	14	110	136	50	2
1200	856	894	905	846	586	842	789	794	787	583	14	105	111	59	3
1350	855	892	902	857	583	842	803	818	804	579	13	89	84	53	4
1500	853	889	899	856	579	843	784	800	777	575	10	105	99	79	4
1650	852	887	894	853	574	846	765	762	723	571	6	122	132	130	3
1800	851	885	890	853	568	848	783	762	760	565	3	102	128	93	3
1950	853	885	887	854	557	853	839	820	799	555		46	67	55	2
2100			894	842	544			889	818	543			5	24	1
2250				854					863					-9	
2400				849					844					5	
2550				842					838					4	
2700				830					827					3	
2850				811					811						
3000															

**NOTE:** Pre-test measurements are taken when the vehicle is in the "As Tested" weight condition. Vehicle measurements forward of the vertical impact reference line are negative. The crush profile grid is established prior to test based on an estimated impact point.

# DATA SHEET NO. 11 (CONTINUED) TEST VEHICLE EXTERIOR CRUSH MEASUREMENTS


Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021



Vehicle Exterior Crush Measurements - Visual Representation

# DATA SHEET NO. 12 MDB EXTERIOR STATIC CRUSH MEASUREMENTS

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021



NOTE: Dimensions are shown in millimeters, mm


### **DEFORMABLE BARRIER STATIC CRUSH**

Stack		Distance Right of Center							C/L			Distar	nce Le	eft of C	Cente	r	
Level	800	700	600	500	400	300	200	100	0	100	200	300	400	500	600	700	800
1	239	234	239	251	262	242	230	224	220	220	222	224	225	228	235	240	236
2	164	168	172	180	181	161	153	146	144	142	144	147	149	151	152	157	164
3	91	78	96	122	150	137	103	78	66	60	58	61	72	89	128	168	175
4	77	63	77	114	141	123	96	85	79	74	82	95	97	114	135	168	187

# DATA SHEET NO. 13 VEHICLE AND MDB DAMAGE PROFILE DISTANCES

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301
Test Program: NCAP Side MDB Impact Test Test Date: 2/5/2021

For guidance regarding damage profile distance measurements, please refer to the latest version of the *NHTSA Test Reference Guide*. *Volume 1: Vehicle Tests*.



#### MEASUREMENT CONVENTIONS:

Forward of the impact point (towards front of vehicle) is considered negative (—). Rearward of the impact point (toward rearend of vehicle) is considered positive (+).

# **VEHICLE DAMAGE PROFILE DISTANCES**

DPD	Distance From Impact Point (mm)	Level	Post-Test (mm)	Pre-Test (mm)	Crush (mm)
1	-150	3	79	92	-13
2	300	3	173	98	75
3	750	3	241	93	148
4	1200	3	206	95	111
5	1650	3	238	106	132
6	2100	3	111	106	5

### MDB DAMAGE PROFILE DISTANCES


DPD	Distance From Center of MDB	Level	Post-Test (mm)*
1	800 mm left of center	1	236
2	480 mm left of center	1	227
3	160 mm left of center	1	221
4	160 mm right of center	1	228
5	480 mm right of center	1	253
6	800 mm right of center	1	239

# DATA SHEET NO. 14 FMVSS NO. 301 STATIC ROLLOVER RESULTS

Test Vehicle: 2021 Mercedes C300 four door sedan NHTSA No.: M20214301 Test Program: Test Date: NCAP Side MDB Impact Test 2/5/2021 Test Time: 10:23 AM Temperature: 21°C A. From impact until vehicle motion ceases: 0 OZ. (Maximum allowable is 1 oz.) B. For the 5-minute period after motion ceases: 0 OZ. (Maximum allowable is 5 oz.) C. For the following 25 minutes: OZ. (Maximum allowable is 1 oz./minute) No Spillage Occurred D. Spillage Details:

### **FMVSS NO. 301 STATIC ROLLOVER DATA**









# **ROLLOVER SOLVENT COLLECTION TIME TABLE IN SECONDS**

Test Phase	Rotation Time	Hold Time	Total Time
0° to 90°	68	300	368
90° to 180°	70	300	370
180° to 270°	62	300	362
270° to 360°	68	300	368

#### **FMVSS NO. 301 ROLLOVER SPILLAGE TABLE**


Test Phase	First 5 Minutes	Sixth Minute	Seventh Minute	Eighth Minute
0° to 90°	0	0	0	
90° to 180°	0	0	0	
180° to 270°	0	0	0	
270° to 360°	0	0	0	

### **ROLLOVER SOLVENT SPILLAGE LOCATION TABLE**

Test Phase	Spillage Location
0° to 90°	None
90° to 180°	None
180° to 270°	None
270° to 360°	None

# DATA SHEET NO. 15 DUMMY/VEHICLE TEMPERATURE AND HUMIDITY STABILIZATION DATA

Test Vehicle:2021 Mercedes C300 four door sedanNHTSA No.:M20214301Test Program:NCAP Side MDB Impact TestTest Date:2/5/2021



Temperature and Humidity Stabilization Chart/Data for Dummies and Test Vehicle

# APPENDIX A PHOTOGRAPHS

# **TABLE OF PHOTOGRAPHS**

Fig.	Description	Page
1	As-Delivered Right Front 3/4 View of Test Vehicle	A-5
2	As-Delivered Left Rear 3/4 View of Test Vehicle	A-5
3	Pre-Test Frontal View of Test Vehicle	A-6
4	Post-Test Frontal View of Test Vehicle	A-6
5	Pre-Test Left Front 3/4 View of Test Vehicle	A-7
6	Post-Test Left Front 3/4 View of Test Vehicle	A-7
7	Pre-Test Left Side View of Test Vehicle	A-8
8	Post-Test Left Side View of Test Vehicle	A-8
9	Pre-Test Left Rear 3/4 View of Test Vehicle	A-9
10	Post-Test Left Rear 3/4 View of Test Vehicle	A-9
11	Pre-Test Rear View of Test Vehicle	A-10
12	Post-Test Rear View of Test Vehicle	A-10
13	Pre-Test Right Side View of Test Vehicle	A-11
14	Post-Test Right Side View of Test Vehicle	A-11
15	Pre-Test Overhead View of Test Area	A-12
16	Post-Test Overhead View of Test Area	A-12
17	Pre-Test Left Side View of MDB Positioned Against Side of Test Vehicle	A-13
18	Pre-Test Right Side View of MDB Positioned Against Side of Test Vehicle	A-13
19	Pre-Test Close-Up View of Impact Point Target	A-14
20	Post-Test Close-up View of Impact Point Target	A-14
21	Pre-Test Left Front Door Latch Close-Up	A-15
22	Post-Test Left Front Door Latch Close-Up	A-15
23	Pre-Test Left Rear Door Latch Close-Up	A-16
24	Post-Test Left Rear Door Latch Close-Up	A-16
25	Pre-Test Front Close-up View of Driver Dummy	A-17
26	Post-Test Front Close-up View of Driver Dummy	A-17
27	Pre-Test Left Side View of Driver Dummy Showing Belt and Chalking	A-18
28	Pre-Test Left Side View of Driver Dummy Shoulder and Door Top View	A-18
29	Post-Test Left Side View of Driver Dummy Shoulder and Door Top View	A-19
30	Pre-Test Frontal View of Driver Seat Back Prior to Dummy Positioning	A-19
31	Pre-Test Frontal View of Driver Dummy Head and Shoulders in Relation to Head Restraint	A-20
32	Pre-Test Frontal View of Driver Seat Pan Prior to Dummy Positioning	A-20
33	Pre-Test Overhead View of Driver Dummy Thighs on Seat Pan	A-21
34	Pre-Test Placement of Driver Dummv's Feet	A-21

Fig.	Description	Page
35	Pre-Test View of Belt Anchorage for Driver Dummy	A-22
36	Pre-Test Left Side View of Steering Wheel	A-22
37	View of Disengaged Parking Brake	A-23
38	Pre-Test View of Parking Brake	A-23
39	Pre-Test Close-Up Left Side View of Driver Seat Track	A-24
40	Pre-Test Close-Up Left Side View of Driver Seat Back	A-24
41	Pre-Test Close-Up View of Driver Seat Back or Head Restraint	A-25
42	Pre-Test Driver Dummy and Door Clearance View	A-25
43	Post-Test Driver Dummy and Door Clearance View	A-26
44	Pre-Test Right Side View of Driver Dummy and Front Seat of Occupant Compartment	A-26
45	Post-Test Right Side View of Driver Dummy and Front Seat of Occupant Compartment	A-27
46	Pre-Test Driver Inner Door Panel View	A-27
47	Post-Test Driver Inner Door Panel View Showing Driver Dummy Contact Locations	A-28
48	Post-Test Driver Dummy Close-Up Head Contact with Vehicle View	A-28
49	Post-Test Driver Dummy Close-Up Head Contact with Side Air bag View	A-29
50	Post-Test Driver Dummy Close-Up Torso Contact with Vehicle Interior View	A-29
51	Post-Test Driver Dummy Close-Up Torso Contact with Side Air bag View	A-30
52	Post-Test Driver Dummy Close-Up Pelvis Contact View	A-30
53	Post-Test Driver Dummy Close-Up Pelvis Contact with Side Air bag View	A-31
54	Post-Test Driver Dummy Close-Up Knee Contact View	A-31
55	Pre-Test Left Side View of Rear Passenger Dummy Showing Belt and Chalking	A-32
56	Pre-Test Left Side View of Rear Passenger Dummy Shoulder and Door Top View	A-32
57	Post-Test Left Side View of Rear Passenger Dummy Shoulder and Door Top View	A-33
58	Pre-Test Frontal View of Rear Passenger Seat Back Prior to Dummy Positioning	A-33
59	Pre-Test Frontal View of Rear Passenger Dummy Head and Shoulders in Relation to Head Restraint	A-34
60	Pre-Test Overhead View of Rear Passenger Seat Pan Prior to Dummy Positioning	A-34
61	Pre-Test Overhead View of Rear Passenger Dummy Thighs on Seat Pan	A-35
62	Pre-Test View of Rear Passenger Dummy's Neck Showing Position of Adjustable Neck Bracket	A-35
63	Pre-Test View of Rear Passenger Dummy's Head Showing Dummy's Head is Level	A-36
64	Pre-Test Placement of Rear Passenger Dummy's Feet	A-36
65	Pre-Test View of Belt Anchorage for Rear Passenger Dummy	A-37
66	Pre-Test Close-Up Left Side View of Rear Passenger Seat Track	A-37
67	Pre-test Close-Up Left Side View of Rear Passenger Seat Back	A-38
68	Pre-Test Close-Up View of Rear Passenger Seat Back or Head Restraint	A-38

Fig.	Description	Page
69	Pre-Test Rear Passenger Dummy and Door Clearance View	A-39
70	Post-Test Rear Passenger Dummy and Door Clearance View	A-39
71	Pre-Test Right Side View of Rear Passenger Dummy and Rear Seat Occupant Compartment	A-40
72	Post-Test Right Side View of Rear Passenger Dummy and Rear Seat Occupant Compartment	A-40
73	Pre-Test Rear Passenger Inner Door Panel View	A-41
74	Post-Test Rear Passenger Inner Door Panel View Showing Rear Passenger Dummy Contact Locations	A-41
75	Post-Test Rear Passenger Dummy Close-Up Head Contact with Vehicle View	A-42
76	Post-Test Rear Passenger Dummy Close-Up Head Contact with Side Air bag View	A-42
77	Post-Test Rear Passenger Dummy Close-Up Torso Contact with Vehicle Interior View	A-43
78	Post-Test Rear Passenger Dummy Close-Up Torso Contact with Side Air bag View	A-43
79	Post-Test Rear Passenger Dummy Close-Up Pelvis Contact View	A-44
80	Post-Test Rear Passenger Dummy Close-Up Pelvis Contact with Side Air bag View	A-44
81	Post-Test Rear Passenger Dummy Close-Up Knee Contact View	A-45
82	Pre-Test View of Fuel Filler Cap or Fuel Filler Neck	A-45
83	Post-Test View of Fuel Filler Cap or Fuel Filler Neck	A-46
84	Pre-Test Front View of MDB Impactor Face	A-46
85	Post-Test Front View of MDB Impactor Face	A-47
86	Pre-Test Top View of MDB Impactor Face	A-47
87	Post-Test Top View of MDB Impactor Face	A-48
88	Pre-Test Left Side View of MDB Impactor Face	A-48
89	Post-Test Left Side View of MDB Impactor Face	A-49
90	Pre-Test Right Side View of MDB Impactor Face	A-49
91	Post-Test Right Side View of MDB Impactor Face	A-50
92	Close-Up View of Vehicle's Certification Label	A-50
93	Close-Up View of Vehicle's Tire Information Placard or Label	A-51
94	Pre-Test Ballast View	A-51
95	Post-Test Primary and Redundant Speed Trap Read-Out	A-52
96	FMVSS No. 301 Static Rollover 0 Degrees	A-52
97	FMVSS No. 301 Static Rollover 90 Degrees	A-53
98	FMVSS No. 301 Static Rollover 180 Degrees	A-53
99	FMVSS No. 301 Static Rollover 270 Degrees	A-54
100	FMVSS No. 301 Static Rollover 360 Degrees	A-54
101	Impact Event	A-55
102	Monroney Label	A-55
103	Driver Head Restraint Use and Adjustment Information from Vehicle Owner's Manual	A-56
104	Left Rear Passenger Head Restraint Use and Adjustment Information from Vehicle Owner's Manual	A-56



Figure A-1: As-Delivered Right Front 3/4 View of Test Vehicle



Figure A-2: As-Delivered Left Rear 3/4 View of Test Vehicle



Figure A-3: Pre-Test Frontal View of Test Vehicle




Figure A-4: Post-Test Frontal View of Test Vehicle



Figure A-5: Pre-Test Left Front 3/4 View of Test Vehicle



Figure A-6: Post-Test Left Front ¾ View of Test Vehicle



Figure A-7: Pre-Test Left Side View of Test Vehicle



Figure A-8: Post-Test Left Side View of Test Vehicle



Figure A-9: Pre-Test Left Rear 3/4 View of Test Vehicle



Figure A-10: Post-Test Left Rear ¾ View of Test Vehicle



Figure A-11: Pre-Test Rear View of Test Vehicle



Figure A-12: Post-Test Rear View of Test Vehicle



Figure A-13: Pre-Test Right Side View of Test Vehicle



Figure A-14: Post-Test Right Side View of Test Vehicle




Figure A-15: Pre-Test Overhead View of the Test Area




Figure A-16: Post-Test Overhead View of Test Area



Figure A-17: Pre-Test Left Side View of MDB Positioned Against Side of Test Vehicle



Figure A-18: Pre-Test Right Side View of MDB Positioned Against Side of Test Vehicle



Figure A-19: Pre-Test Close-up View of Impact Point Target




Figure A-20: Post-Test Close-up View of Impact Point Target




Figure A-21: Pre-Test Left Front Door Latch Close-Up




Figure A-22: Post-Test Left Front Door Latch Close-Up



Figure A-23: Pre-Test Left Rear Door Latch Close-Up



Figure A-24: Post-Test Left Rear Door Latch Close-Up



Figure A-25: Pre-Test Front Close-up View of Driver Dummy



Figure A-26: Post-Test Front Close-up View of Driver Dummy



Figure A-27: Pre-Test Left Side View of Driver Dummy Showing Belt and Chalking



Figure A-28: Pre-Test Left Side View of Driver Dummy Shoulder and Door Top View



Figure A-29: Post-Test Left Side View of Driver Dummy Shoulder and Door Top View



Figure A-30: Pre-Test Frontal View of Driver Seat Back Prior to Dummy Positioning




Figure A-31: Pre-Test Frontal View of Driver Dummy Head and Shoulders in Relation to Head Restraint



Figure A-32: Pre-Test Frontal View of Driver Seat Pan Prior to Dummy Positioning



Figure A-33: Pre-Test Overhead View of Driver Dummy Thighs on Seat Pan




Figure A-34: Pre-Test Placement of Driver Dummy's Feet



Figure A-35: Pre-Test View of Belt Anchorage for Driver Dummy



Figure A-36: Pre-Test Left Side View of Steering Wheel



Figure A-37: View of Disengaged Parking Brake



Figure A-38: Pre-Test View of Parking Brake




Figure A-39: Pre-test Close-Up Left Side View of Driver Seat Track



Figure A-40: Pre-Test Close-Up Left Side View of Driver Seat Back



Figure A-41: Pre-Test Close-Up View of Driver Seat Back or Head Restraint



Figure A-42: Pre-Test Driver Dummy and Door Clearance View



Figure A-43: Post-Test Driver Dummy and Door Clearance View



Figure A-44: Pre-Test Right Side View of Driver Dummy and Front Seat of Occupant Compartment



Figure A-45: Post-Test Right Side View of Driver Dummy and Front Seat of Occupant Compartment



Figure A-46: Pre-Test Driver Inner Door Panel View



Figure A-47: Post-Test Driver Inner Door Panel View Showing Driver Dummy Contact Locations



Figure A-48: Post-Test Driver Dummy Close-Up Head Contact with Vehicle View



Figure A-49: Post-Test Driver Dummy Close-Up Head Contact with Side Air bag View



Figure A-50: Post-Test Driver Dummy Close-Up Torso Contact with Vehicle Interior View



Figure A-51: Post-Test Driver Dummy Close-Up Torso Contact with Side Air bag View



Figure A-52: Post-Test Driver Dummy Close-Up Pelvis Contact View



Figure A-53: Post-Test Driver Dummy Close-Up Pelvis Contact with Side Air bag View




Figure A-54: Post-Test Driver Dummy Close-Up Knee Contact View



Figure A-55: Pre-Test Left Side View of Rear Passenger Dummy Showing Belt and Chalking



Figure A-56: Pre-Test Left Side View of Rear Passenger Dummy Shoulder and Door Top View



Figure A-57: Post-Test Left Side View of Rear Passenger Dummy Shoulder and Door Top View



Figure A-58: Pre-Test Frontal View of Rear Passenger Seat Back Prior to Dummy Positioning




Figure A-59: Pre-Test Frontal View of Rear Passenger Dummy Head and Shoulders in Relation to Head Restraint



Figure A-60: Pre-Test Overhead View of Rear Passenger Seat Pan Prior to Dummy Positioning



Figure A-61: Pre-Test Overhead View of Rear Passenger Dummy Thighs on Seat Pan



Figure A-62: Pre-Test View of Rear Passenger Dummy's Neck Showing Position of Adjustable Neck Bracket




Figure A-63: Pre-Test View of Rear Passenger Dummy's Head Showing Dummy's Head is Level



Figure A-64: Pre-Test Placement of Rear Passenger Dummy's Feet



Figure A-65: Pre-Test View of Belt Anchorage for Rear Passenger Dummy



Figure A-66: Pre-Test Close-Up Left Side View of Rear Passenger Seat Track



Figure A-67: Pre-Test Close-Up Left Side View of Rear Passenger Seat Back



Figure A-68: Pre-Test Close-Up View of Rear Passenger Seat Back or Head Restraint



Figure A-69: Pre-Test Rear Passenger Dummy and Door Clearance View





Figure A-71: Pre-Test Right Side View of Rear Passenger Dummy and Rear Seat Occupant Compartment



Figure A-72: Post-Test Right Side View of Rear Passenger Dummy and Rear Seat
Occupant Compartment



Figure A-73: Pre-Test Rear Passenger Inner Door Panel View



Figure A-74: Post-Test Rear Passenger Inner Door Panel View Showing Rear Passenger Dummy Contact Locations



Figure A-75: Post-Test Rear Passenger Dummy Close-Up Head Contact with Vehicle View



Figure A-76: Post-Test Rear Passenger Dummy Close-Up Head Contact with Side Air bag View



Figure A-77: Post-Test Rear Passenger Dummy Close-Up Torso Contact with Vehicle Interior View




Figure A-78: Post-Test Rear Passenger Dummy Close-Up Torso Contact with Side Air bag View



Figure A-79: Post-Test Rear Passenger Dummy Close-Up Pelvis Contact View



Figure A-80: Post-Test Rear Passenger Dummy Close-Up Pelvis Contact with Side Air bag View



Figure A-81: Post-Test Rear Passenger Dummy Close-Up Knee Contact View





Figure A-83: Post-Test View of Fuel Filler Cap or Fuel Filler Neck



Figure A-84: Pre-Test Front View of MDB Impactor Face



Figure A-85: Post-Test Front View of MDB Impactor Face



Figure A-86: Pre-Test Top View of MDB Impactor Face



Figure A-87: Post-Test Top View of MDB Impactor Face



Figure A-88: Pre-Test Left Side View of MDB Impactor Face



Figure A-89: Post-Test Left Side View of MDB Impactor Face



Figure A-90: Pre-Test Right Side View of MDB Impactor Face



Figure A-91: Post-Test Right Side View of MDB Impactor Face



Figure A-92: Close-Up View of Vehicle's Certification Label




Figure A-93: Close-Up View of Vehicle's Tire Information Placard or Label



Figure A-94: Pre-Test Ballast View



Figure A-95: Post-Test Primary and Redundant Speed Trap Read-Out



Figure A-96: FMVSS No. 301 Static Rollover 0 Degrees



Figure A-97: FMVSS No. 301 Static Rollover 90 Degrees




Figure A-98: FMVSS No. 301 Static Rollover 180 Degrees






Figure A-100: FMVSS No. 301 Static Rollover 360 Degrees



Figure A-101: Impact Event





Figure A-102: Monroney Label



To move backwards: press and hold release

knob 2.

direction of the arrow and push the head

restraint down.

that it is as close as possible to the back of your

head.

Figure A-103: Driver Head Restraint Use and Adjustment Information from Vehicle Owner's Manual




Figure A-104: Left Rear Passenger Head Restraint Use and Adjustment Information from **Vehicle Owner's Manual-Rear Restraints Not Adjustable** 

#### **APPENDIX B**

VEHICLE AND DUMMY RESPONSE DATA PLOTS

# **TABLE OF DATA PLOTS**

# **Driver & Passenger Dummy Instrumentation Plots**

Description	Page
Driver Head Acceleration (X) Primary vs. Time	B-5
Driver Head Acceleration (Y) Primary vs. Time	B-5
Driver Head Acceleration (Z) Primary vs. Time	B-5
Driver Head Resultant Acceleration Primary vs. Time	B-5
Driver Upper Thorax Rib Deflection (Y) vs. Time	B-6
Driver Middle Thorax Rib Deflection (Y) vs. Time	B-6
Driver Lower Thorax Rib Deflection (Y) vs. Time	B-6
Driver Thorax Rib Deflection Maximum vs. Time	B-6
Driver Anterior Abdominal Force (Y) vs. Time	B-7
Driver Middle Abdominal Force (Y) vs. Time	B-7
Driver Posterior Abdominal Force (Y) vs. Time	B-7
Driver Total Abdominal Force (Y) vs. Time	B-7
Driver Pubic Symphysis Force (Y) vs. Time	B-8
Passenger Head Acceleration (X) vs. Time Primary	B-8
Passenger Head Acceleration (Y) vs. Time Primary	B-8
Passenger Head Acceleration (Z) vs. Time Primary	B-8
Passenger Head Resultant Acceleration Primary vs. Time	B-9
Passenger Lower Spine T12 Acceleration (X) vs. Time	B-9
Passenger Lower Spine T12 Acceleration (Y) vs. Time	B-9
Passenger Lower Spine T12 Acceleration (Z) vs. Time	B-9
Passenger Lower Spine T12 Resultant Acceleration vs. Time	B-10
Passenger Iliac Force on Impact Side (Y) vs. Time	B-10
Passenger Acetabulum Force on Impact Side (Y) vs. Time	B-10
Passenger Total Pelvic Force on Impact Side (Y) vs. Time	B-10
	Driver Head Acceleration (X) Primary vs. Time Driver Head Acceleration (Y) Primary vs. Time Driver Head Acceleration (Z) Primary vs. Time Driver Head Resultant Acceleration Primary vs. Time Driver Upper Thorax Rib Deflection (Y) vs. Time Driver Middle Thorax Rib Deflection (Y) vs. Time Driver Lower Thorax Rib Deflection (Y) vs. Time Driver Lower Thorax Rib Deflection (Y) vs. Time Driver Anterior Abdominal Force (Y) vs. Time Driver Middle Abdominal Force (Y) vs. Time Driver Posterior Abdominal Force (Y) vs. Time Driver Posterior Abdominal Force (Y) vs. Time Driver Pubic Symphysis Force (Y) vs. Time Driver Pubic Symphysis Force (Y) vs. Time Passenger Head Acceleration (X) vs. Time Primary Passenger Head Acceleration (Z) vs. Time Primary Passenger Head Resultant Acceleration Primary vs. Time Passenger Lower Spine T12 Acceleration (X) vs. Time Passenger Lower Spine T12 Acceleration (Z) vs. Time Passenger Lower Spine T12 Resultant Acceleration vs. Time

# The following additional data for this test can be obtained from the Research and Development section of the NHTSA website. The website can be found at www.NHTSA.gov.

#### **Additional Driver & Passenger Dummy Instrumentation Data**

Driver Lower Spine T12 Acceleration (X)

Driver Lower Spine T12 Acceleration (Y)

Driver Lower Spine T12 Acceleration (Z)

Passenger Upper Thorax Rib Deflection (Y)

Passenger Middle Thorax Rib Deflection (Y)

Passenger Lower Thorax Rib Deflection (Y)

Passenger Upper Abdomen Rib Deflection (Y)

Passenger Lower Abdomen Rib Deflection (Y)

Driver Head Acceleration Redundant (X)

Driver Head Acceleration Redundant (Y)

Driver Head Acceleration Redundant (Z)

Passenger Head Acceleration Redundant (X)

Passenger Head Acceleration Redundant (Y)

Passenger Head Acceleration Redundant (Z)

#### **Vehicle Instrumentation Data**

Vehicle Center of Gravity Acceleration (X)

Vehicle Center of Gravity Acceleration (Y)

Vehicle Center of Gravity Acceleration (Z)

Right Side Sill at Front Seat Acceleration (X)

Right Side Sill at Front Seat Acceleration (Y)

Right Side Sill at Front Seat Acceleration (Z)

Right Side Sill at Rear Seat Acceleration (X)

Right Side Sill at Rear Seat Acceleration (Y)

Right Side Sill at Rear Seat Acceleration (Z)

Left Side Sill at Front Seat Acceleration (Y)

Left Side Sill at Rear Seat Acceleration (Y)

Lower A-Post Acceleration (Y)

Middle A-Post Acceleration (Y)

Lower B-Post Acceleration (Y)

Middle B-Post Acceleration (Y)

Front Seat Track Acceleration (Y)

Rear Seat Structure Acceleration (Y)

Right Rear Occupant Compartment Acceleration (Y)

Engine Block (X)

Engine Block (Y)

Rear Floorpan Above Axle Acceleration (X)

Rear Floorpan Above Axle Acceleration (Y)

Rear Floorpan Above Axle Acceleration (Z)

#### **MDB Instrumentation Data**

MDB Center of Gravity Acceleration (X)

MDB Center of Gravity Acceleration (Y)

MDB Center of Gravity Acceleration (Z)


MDB Rear Acceleration (X)

MDB Rear Acceleration (Y)


Left MDB Contact Switch

Right MDB Contact Switch
































# APPENDIX C DUMMY PERFORMANCE CALIBRATION TEST DATA

## **CALIBRATION TEST RESULTS**

## PRE-TEST

## EUROSID 2 (ES-2RE) MALE – DRIVER ATD

SERIAL NO: F034


(CONFIGURED FOR LEFT SIDE IMPACT)



#### External Measurements - EuroSID-2re

Technician: K. Brogan Date: 1/15/2021

Dummy Serial Number: F034



FRONT VIEW

SIDE VIEW

Dim. No.	Description	10.00	ication m)	Result (mm)	Pass/Fail
1	Sitting Height	900	918	914	Pass
2	Seat to Shoulder Joint	558	572	569	Pass
3	Seat to Lower Face of Thoracic Spine Box	346	356	352	Pass
4	Seat to Hip Joint (center of bolt)	97	103	100	Pass
5	Sole to Seat, Sitting	333	451	425	Pass
6	Head Width	152	158	155	Pass
7	Shoulder/Arm Width	461	479	473	Pass
8	Thorax Width	322	332	329	Pass
9	Abdomen Width	273	287	285	Pass
10	Pelvis Lap Width	359	373	367	Pass
11	Head Depth	196	206	203	Pass
12	Thorax Depth	262	272	268	Pass
13	Abdomen Depth	194	204	202	Pass
14	Pelvis Depth	235	245	240	Pass
15	Back of Buttocks to Hip Joint (center of bolt)	150	160	156	Pass
16	Back of Buttocks to Front Knee	597	615	609	Pass


#### Certification Report ES-2re Head Drop - CFR 572

ATD Manufacturer	FTSS	Test Technician	S. Vacanti
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan


#### Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.9	Pass
Humidity	10	70	%	21	Pass
Resultant Acceleration	125	155	g's	141.9	Pass
Oscillation	0	15	%	1.12	Pass
Fore-Aft Acceleration	-15	15	g's	8.7	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
X Accelerometer	Endevco 7264C	P51884	9/22/2020	3/23/2021
Y Accelerometer	Endevco 7264C	P73161	9/22/2020	3/23/2021
Z Accelerometer	Endevco 7264C	P79588	9/22/2020	3/23/2021










#### Certification Report ES-2re Neck Flexion - CFR 572

ATD Manufacturer	FTSS	Test Technician	E. Helenbrook
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan


#### Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.8	Pass
Humidity	10	70	%	23.2	Pass
Velocity	3.3	3.5	m/s	3.38	Pass
Lateral Neck Rotation	49	59	deg	52.2	Pass
Time at Maximum Rotation	54	66	ms	57.4	Pass
Time of Rotation Decay from Maximum	53	88	ms	56.1	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Pendulum Accelerometer	ENDEVCO 7231CT	AC-C16503	2/5/2021	2/5/2022
Front Pendulum Potentiometer	SP22G	DS-094	8/18/2020	8/18/2021
Headform Potentiometer	SP22G	DS-095	8/18/2020	8/18/2021










# Certification Report ES-2re Shoulder Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

#### Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	25.0	Pass
Velocity	4.2	4.4	m/s	4.39	Pass
Probe Acceleration	7.5	10.5	g's	9.01	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Probe Accelerometer	ENDEVCO 7264C	T25885	2/2/2021	2/2/2022






#### Certification Report ES-2re Upper Rib Drop 3 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

#### Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.7	Pass
Humidity	10	70	%	20.9	Pass
Rib Displacement	36	40	mm	37.4	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date	
Rib Potentiometer	Honeywell MLT-38000203	DS-183GFE	10/8/2020	4/8/2021	






#### Certification Report ES-2re Upper Rib Drop 4 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

#### Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.6	Pass
Humidity	10	70	%	21.7	Pass
Rib Displacement	46	51	mm	48.7	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Rib Potentiometer	Honeywell MLT-38000203	DS-183GFE	10/8/2020	4/8/2021





# Certification Report ES-2re Middle Rib Drop 3 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

# Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.0	Pass
Humidity	10	70	%	23.4	Pass
Rib Displacement	36	40	mm	37.8	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Rib Potentiometer	Honeywell MLT-38000203	DS-184GFE	10/8/2020	4/8/2021





# Certification Report ES-2re Middle Rib Drop 4 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

#### Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.2	Pass
Humidity	10	70	%	22.1	Pass
Rib Displacement	46	51	mm	48.3	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Rib Potentiometer	Honeywell MLT-38000203	DS-184GFE	10/8/2020	4/8/2021






# Certification Report ES-2re Lower Rib Drop 3 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

# Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.0	Pass
Humidity	10	70	%	23.4	Pass
Rib Displacement	36	40	mm	38.3	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Rib Potentiometer	Honeywell MLT-38000203	DS-182GFE	10/8/2020	4/8/2021





# Certification Report ES-2re Lower Rib Drop 4 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

# Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.0	Pass
Humidity	10	70	%	23.4	Pass
Rib Displacement	46	51	mm	49.1	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Rib Potentiometer	Honeywell MLT-38000203	DS-182GFE	10/8/2020	4/8/2021






# Certification Report ES-2re Thorax Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan


# Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	26.0	Pass
Velocity	5.4	5.6	m/s	5.44	Pass
Resistive Force after 6ms	5100	6200	N	5651.6	Pass
Upper Thorax Rib Deflection	34	41	mm	38.3	Pass
Mid Thorax Rib Deflection	37	45	mm	42.0	Pass
Lower Thorax Rib Deflection	37	44	mm	41.7	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Probe Accelerometer	ENDEVCO 7264C-2K-TZ2	T25885	2/2/2021	2/2/2022
Upper Thorax Rib Potentiometer	Honeywell MLT-38000203	DS-183GFE	10/8/2020	4/8/2021
Middle Thorax Rib Potentiometer	Honeywell MLT-38000203	DS-184GFE	10/8/2020	4/8/2021
Lower Thorax Rib Potentiometer	Honeywell MLT-38000203	DS-182GFE	10/8/2020	4/8/2021










# Certification Report ES-2re Abdomen Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	F034	Laboratory Supervisor	K.Brogan


#### Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	26	Pass
Velocity	3.9	4.1	m/s	4.09	Pass
Combined Abdomen Force	2200	2700	N	2505.3	Pass
Time at Peak Abdomen Force	10.0	12.3	ms	11.05	Pass
Resistive Probe Force	4000	4800	N	4580.3	Pass
Time at Peak Resistive Force	10.6	13.0	ms	11.50	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Pendulum Accelerometer	ENDEVCO 7264C	T25885	2/2/2021	2/2/2022
Front Abdomen Load Cell	DENTON 2631J	LC-1524	3/19/2020	3/19/2021
Middle Abdomen Load Cell	DENTON 2631J	LC-1523	3/19/2020	3/19/2021
Rear Abdomen Load Cell	DENTON 2631J	LC-1530	3/19/2020	3/19/2021









# Certification Report ES-2re Spine Flexion - CFR 572


ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

# Results


Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.9	Pass
Humidity	10	70	%	22.3	Pass
Velocity	5.95	6.15	m/s	6.046	Pass
Lateral Spine Rotation	45	55	deg	46.9	Pass
Time at Maximum Rotation	39	53	ms	43.0	Pass
Time of Decay to Zero Degrees	37	57	ms	37.4	Pass
Pulse within Corridor?		-	-		

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Pendulum Accelerometer	ENDEVCO 7231CT	AC-C16503 Striker	2/5/2021	2/5/2022
Pendulum "A" Potentiomete	SP22G	DS-094	8/18/2020	8/18/2021
Condyle "B" Potentiometer	SP22G	DS-095	8/18/2020	8/18/2021












# Certification Report ES-2re Pelvis Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan


#### Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	26.0	Pass
Velocity	4.2	4.4	m/s	4.37	Pass
Resistive Force	4700	5400	N	4920.3	Pass
Time at Peak Resistive Force	11.8	16.1	ms	12.80	Pass
Pubic Force	-1590	-1230	N	-1469.2	Pass
Time at Peak Pubic Force	12.2	17.0	ms	13.60	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Pendulum Accelerometer	ENDEVCO 7264C	T25885	2/2/2021	2/2/2022
Pubic Load Cell	Denton 3096JFL	30960459GFE	3/19/2020	3/19/2021







# **CALIBRATION TEST RESULTS**

# PRE-TEST

# SID-IIS 5TH PERCENTILE FEMALE - PASSENGER ATD

SERIAL No: 300


(CONFIGURED FOR LEFT SIDE IMPACT)




# External Measurements - SID-IIs

Technician: K. Dutton Date: 01/15/2021

Dummy Serial Number: 300





Symbol	Description		ication m)	Result (mm)	Pass/Fail
	Sitting Height	772	788	781	Pass
В	Shoulder Pivot Height	437	453	440	Pass
С	H-point Height	79	89	85	Pass
D	H-point from seatback	141	151	145	Pass
E	Shoulder Pivot from Backline	97	107	102	Pass
F	Thigh Clearance	119	135	126	Pass
G	Head Breadth	140	148	144	Pass
Н	Head Back from Backline	40	46	43	Pass
1	Head Depth	178	188	187	Pass
J	Head Circumference	541	551	544	Pass
K	Buttock to Knee Length	514	540	532	Pass
L	Popliteal Height	343	369	361	Pass
M	Knee Pivot to floor height	392	409	398	Pass
N	Buttock Popliteal Length	416	442	430	Pass
0	Chest Depth w/o jacket	195	211	208	Pass
Р	Foot Length	216	232	220	Pass
Q	Hip Breadth (w/pelvic plugs)	313	323	317	Pass
R	Arm Length	249	259	254	Pass
S	Knee Joint to seatback	477	493	484	Pass
V	Shoulder Width	341	357	352	Pass
W	Foot Width	78	94	83	Pass
Y	Chest Circumference w/jacket	851	881	875	Pass
Z	Waist Circumference	761	791	773	Pass




# Certification Report SID-IIs Lateral Head Drop Left- CFR 572

ATD Manufacturer	FTSS	Test Technician	S. Vacanti
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


# Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.9	Pass
Humidity	10	70	%	29	Pass
Resultant Acceleration	115	137	g's	125.7	Pass
Oscillation	0	15	%	1.1	Pass
Fore-Aft Acceleration	-15	15	g's	-4.2	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
X Accelerometer	ENDEVCO 7264CT	AC-P59018	11/10/2020	5/11/2021
Y Accelerometer	ENDEVCO 7264	AC-P79189	11/10/2020	5/11/2021
Z Accelerometer	ENDEVCO 7264CT	AC-P58777	11/10/2020	5/11/2021










# Certification Report SID-IIs Neck Flexion Left- CFR 572

ATD Manufacturer	FTSS	Test Technician	S. Vacanti
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


# Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.9	Pass
Humidity	10	70	%	29	Pass
Velocity	5.51	5.63	m/s	5.549	Pass
Pendulum Impulse at 10ms	2.2	2.8	m/s	2.22	Pass
Pendulum Impulse at 15ms	3.3	4.1	m/s	3.35	Pass
Pendulum Impulse at 20ms	4.4	5.4	m/s	4.52	Pass
Pendulum Impulse at 25ms	5.4	6.1	m/s	5.44	Pass
Pendulum Impulse from 25 to 100ms	5.5	6.2	m/s	6.02	Pass
Neck Rotation	71	81	deg	71.3	Pass
Time at Maximum Rotation	50	70	ms	60.1	Pass
Moment about the OC	36	44	Nm	42.1	Pass
Moment Decay to 0 Nm	102	126	ms	111.1	Pass

Channel	Manufacturer	Serial	Calibration	Calibration
		Number	Date	Due Date
Pendulum Accelerometer	ENDEVCO 7231CT	AC-C16503 Striker	2/6/2020	2/5/2021
Pendulum Potentiometer	Denton 78051-342	DS-184Pend	11/6/2020	11/6/2021
Condyle Potentiometer	Denton 78051-342	DS-185Pend	11/6/2020	11/6/2021
Upper Neck Load Cell	Denton 1716	17162019 FY	3/18/2020	3/18/2021










# Certification Report SID-IIs Shoulder Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	S. Vacanti
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


# Results


Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.9	Pass
Humidity	10	70	%	29	Pass
Velocity	4.2	4.4	m/s	4.31	Pass
Probe Acceleration	13	18	g's	15.8	Pass
Shoulder Deflection	28	37	mm	29.3	Pass
Lateral Upper Spine Acceleration	17	22	g's	20.8	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Pendulum Accelerometer	MSI 64C-2000	A286228	1/29/2020	1/28/2021
Shoulder Potentiometer	Servo 08CT1-3725	DS-053 GFE	11/10/2020	5/11/2021
Upper Spine Y Accelerometer	ENDEVCO 7264CT	AC-P71281	11/9/2020	5/10/2021












# Certification Report SID-IIs Thorax With Arm Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	S. Vacanti
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


# Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.9	Pass
Humidity	10	70	%	29.0	Pass
Velocity	6.6	6.8	m/s	6.71	Pass
Probe Acceleration after 5 ms	30	36	g's	34.4	Pass
Lateral Upper Spine Acceleration	34	43	g's	41.2	Pass
Lateral Lower Spine Acceleration	29	37	g's	32.4	Pass
Shoulder Deflection	31	40	mm	33.7	Pass
Upper Thorax Rib Deflection	25	32	mm	26.0	Pass
Mid Thorax Rib Deflection	30	36	mm	30.9	Pass
Lower Thorax Rib Deflection	32	38	mm	32.7	Pass


Channel	Manufacturer	Serial	Calibration	Calibration
		Number	Date	Due Date
Pendulum Accelerometer	MSI 64C-2000	A286228	1/29/2020	1/28/2021
Upper Spine T1 Y Accelerometer	ENDEVCO 7264CT	AC-P71281	11/9/2020	5/10/2021
Upper Spine T12 Y Accelerometer	ENDEVCO 7264	AC-P64147	11/9/2020	5/10/2021
Shoulder Potentiometer	Servo 08CT1-3725	DS-053 GFE	11/10/2020	5/11/2021
Upper Thorax Rib Potentiometer	Servo 08CT1-3725	DS-451GFE	11/10/2020	5/11/2021
Middle Thorax Rib Potentiometer	Servo 08TC1-3745	DS-040GFE	11/10/2020	5/11/2021
Lower Thorax Rib Potentiometer	Servo 08TC1-3725	DS-1156GFE	11/9/2020	5/10/2021














# Certification Report SID-IIs Thorax Without Arm Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	S. Vacanti
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


# Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.9	Pass
Humidity	10	70	%	29	Pass
Velocity	4.2	4.4	m/s	4.36	Pass
Probe Acceleration	14	18	g's	16.3	Pass
Lateral Upper Spine Acceleration	13	17	g's	15.8	Pass
Lateral Lower Spine Acceleration	7	11	g's	9.7	Pass
Upper Thorax Rib Deflection	32	40	mm	34.0	Pass
Middle Thorax Rib Deflection	39	45	mm	39.9	Pass
Lower Thorax Rib Deflection	35	43	mm	36.8	Pass


Channel	Manufacturer	Serial	Calibration	Calibration
		Number	Date	Due Date
Pendulum Accelerometer	MSI 64C-2000	A286228	1/29/2020	1/28/2021
Upper Spine Y Accelerometer	ENDEVCO 7264CT	AC-P71281	11/9/2020	5/10/2021
Lower Spine Y Accelerometer	ENDEVCO 7264	AC-P64147	11/9/2020	5/10/2021
Upper Thorax Rib Potentiometer	Servo 08CT1-3725	DS-451GFE	11/10/2020	5/11/2021
Middle Thorax Rib Potentiometer	Servo 08TC1-3745	DS-040GFE	11/10/2020	5/11/2021
Lower Thorax Rib Potentiometer	Servo 08TC1-3725	DS-1156GFE	11/9/2020	5/10/2021












# Certification Report SID-IIs Abdommen Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	S. Vacanti
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


# Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.9	Pass
Humidity	10	70	%	29.0	Pass
Velocity	4.2	4.4	m/s	4.31	Pass
Probe Acceleration	12	16	g's	14.0	Pass
Lateral Lower Spine Acceleration	9	14	g's	11.4	Pass
Upper Abdomen Rib Deflection	36	47	mm	39.8	Pass
Lower Abdomen Rib Deflection	33	44	mm	41.0	Pass


Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Probe Accelerometer	MSI 64C-2000	A286228	1/29/2020	1/28/2021
Lower Spine Y Accelerometer	ENDEVCO 7264	AC-P64147	11/9/2020	5/10/2021
Upper Abdomen Rib Potentiometer	Servo 08CT1-3725	DS-308GFE	11/10/2020	5/11/2021
Lower Abdomen Rib Potentiometer	Servo 08CT1-3725	DS-307GFE	11/10/2020	5/11/2021














# Certification Report SID-IIs Acetabulum Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	S. Vacanti
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


# Results


Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.9	Pass
Humidity	10	70	%	29	Pass
Velocity	6.6	6.8	m/s	6.70	Pass
Probe Acceleration	38	47	g's	44.7	Pass
Lateral Pelvis Acceleration after 6ms	34	42	g's	36.9	Pass
Acetabulum Force	3600	4300	N	3908.7	Pass


Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Pendulum Accelerometer	MSI 64C-2000	A286228	1/29/2020	1/28/2021
Pelvis Y Accelerometer	ENDEVCO 7264C	AC-P51731	11/9/2020	5/10/2021
Acetabulum Load Cell	Denton IF-520	LC-236Fy	3/18/2020	3/18/2021
Certification Plug	SACO	13968	5/22/2020	N/A
Crash Test Plug	SACO	13933	5/20/2020	N/A

















# Certification Report SID-IIs Iliac Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	K. Brogan
ATD Serial Number	300	Laboratory Supervisor	S. Vacanti


# Results

110011110						
Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail		
20.6	22.2	°C	20.9	Pass		
10	70	%	29.0	Pass		
4.2	4.4	m/s	4.26	Pass		
36	45	g's	43.7	Pass		
28	39	g's	35.2	Pass		
4100	5100	N	4915.0	Pass		
	20.6 10 4.2 36 28	Specification         Specification           20.6         22.2           10         70           4.2         4.4           36         45           28         39	Specification         Specification           20.6         22.2         °C           10         70         %           4.2         4.4         m/s           36         45         g's           28         39         g's	Specification         Specification           20.6         22.2         °C         20.9           10         70         %         29.0           4.2         4.4         m/s         4.26           36         45         g's         43.7           28         39         g's         35.2		

Channel	Manufacturer	Serial	Calibration	Calibration
		Number	Date	Due Date
Pendulum Accelerometer	MSI 64C-2000	A286228	1/29/2020	1/28/2021
Pelvis Y Accelerometer	ENDEVCO 7264C	AC-P51731	11/9/2020	5/10/2021
Iliac Load Cell	DENTON 3228J	LC-279Fy	11/23/2020	11/23/2021







# **CALIBRATION TEST RESULTS**

# **POST-TEST**

# EUROSID 2 (ES-2RE) MALE – DRIVER ATD

SERIAL NO: F034


(CONFIGURED FOR LEFT SIDE IMPACT)



## External Measurements - EuroSID-2re

Technician: K. Dutton Date: 2/5/2021

Dummy Serial Number: F034



FRONT VIEW

SIDE VIEW

Dim. No.	Description	Specification (mm)		Result (mm)	Pass/Fail
1	Sitting Height	900	918	914	Pass
2	Seat to Shoulder Joint	558	572	569	Pass
3	Seat to Lower Face of Thoracic Spine Box	346	356	352	Pass
4	Seat to Hip Joint (center of bolt)	97	103	100	Pass
5	Sole to Seat, Sitting	333	451	425	Pass
6	Head Width	152	158	154	Pass
7	Shoulder/Arm Width	461	479	472	Pass
8	Thorax Width	322	332	329	Pass
9	Abdomen Width	273	287	285	Pass
10	Pelvis Lap Width	359	373	367	Pass
11	Head Depth	196	206	202	Pass
12	Thorax Depth	262	272	268	Pass
13	Abdomen Depth	194	204	202	Pass
14	Pelvis Depth	235	245	240	Pass
15	Back of Buttocks to Hip Joint (center of bolt)	150	160	156	Pass
16	Back of Buttocks to Front Knee	597	615	609	Pass




## Certification Report ES-2re Head Drop - CFR 572

ATD Manufacturer	FTSS	Test Technician	S. Vacanti
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan


## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.9	Pass
Humidity	10	70	%	22	Pass
Resultant Acceleration	125	155	g's	138.9	Pass
Oscillation	0	15	%	2.86	Pass
Fore-Aft Acceleration	-15	15	g's	9.7	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
X Accelerometer	Endevco 7264C	P51884	9/22/2020	3/23/2021
Y Accelerometer	Endevco 7264C	P73161	9/22/2020	3/23/2021
Z Accelerometer	Endevco 7264C	P79588	9/22/2020	3/23/2021








## Certification Report ES-2re Neck Flexion - CFR 572

ATD Manufacturer	FTSS	Test Technician	E. Helenbrook
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan


## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.8	Pass
Humidity	10	70	%	23.2	Pass
Velocity	3.3	3.5	m/s	3.38	Pass
Lateral Neck Rotation	49	59	deg	52.3	Pass
Time at Maximum Rotation	54	66	ms	59.2	Pass
Time of Rotation Decay from Maximum	53	88	ms	54.7	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Pendulum Accelerometer	ENDEVCO 7231CTA	C-C16503 Strik	er 2/5/2021	2/5/2022
Front Pendulum Potentiometer	SP22G	DS-094	8/18/2020	8/18/2021
Headform Potentiometer	SP22G	DS-095	8/18/2020	8/18/2021










# Certification Report ES-2re Shoulder Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	24.0	Pass
Velocity	4.2	4.4	m/s	4.40	Pass
Probe Acceleration	7.5	10.5	g's	9.57	Pass

Channel	Manufacturer	Serial Number		
Probe Accelerometer	ENDEVCO 7264C	T25885	2/2/2021	2/2/2022





## Certification Report ES-2re Upper Rib Drop 3 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.7	Pass
Humidity	10	70	%	20.9	Pass
Rib Displacement	36	40	mm	37.5	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Rib Potentiometer	Honeywell MLT-38000203	DS-183GFE	10/8/2020	4/8/2021






## Certification Report ES-2re Upper Rib Drop 4 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.6	Pass
Humidity	10	70	%	21.7	Pass
Rib Displacement	46	51	mm	48.4	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Rib Potentiometer	Honeywell MLT-38000203	DS-183GFE	10/8/2020	4/8/2021





## Certification Report ES-2re Middle Rib Drop 3 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.0	Pass
Humidity	10	70	%	23.4	Pass
Rib Displacement	36	40	mm	37.8	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Rib Potentiometer	Honeywell MLT-38000203	DS-184GFE	10/8/2020	4/8/2021






## Certification Report ES-2re Middle Rib Drop 4 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.0	Pass
Humidity	10	70	%	23.4	Pass
Rib Displacement	46	51	mm	48.5	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Rib Potentiometer	Honeywell MLT-38000203	DS-184GFE	10/8/2020	4/8/2021





## Certification Report ES-2re Lower Rib Drop 3 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.0	Pass
Humidity	10	70	%	23.4	Pass
Rib Displacement	36	40	mm	38.4	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Rib Potentiometer	Honeywell MLT-38000203	DS-182GFE	10/8/2020	4/8/2021






## Certification Report ES-2re Lower Rib Drop 4 m/s - CFR 572

ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.0	Pass
Humidity	10	70	%	23.4	Pass
Rib Displacement	46	51	mm	49.2	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Rib Potentiometer	Honeywell MLT-38000203	DS-182GFE	10/8/2020	4/8/2021




## Certification Report ES-2re Thorax Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan


## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	26.0	Pass
Velocity	5.4	5.6	m/s	5.44	Pass
Resistive Force after 6ms	5100	6200	N	5711.5	Pass
Upper Thorax Rib Deflection	34	41	mm	37.6	Pass
Mid Thorax Rib Deflection	37	45	mm	41.9	Pass
Lower Thorax Rib Deflection	37	44	mm	41.2	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date	
Probe Accelerometer	ENDEVCO 7264C-2K-TZ2	T25885	2/2/2021	2/2/2022	
Upper Thorax Rib Potentiometer	Honeywell MLT-38000203	DS-183GFE	10/8/2020	4/8/2021	
Middle Thorax Rib Potentiometer	Honeywell MLT-38000203	DS-184GFE	10/8/2020	4/8/2021	
Lower Thorax Rib Potentiometer	Honeywell MLT-38000203	DS-182GFE	10/8/2020	4/8/2021	










## Certification Report ES-2re Abdomen Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	FO34	Laboratory Supervisor	K.Brogan


#### Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	26	Pass
Velocity	3.9	4.1	m/s	4.09	Pass
Combined Abdomen Force	2200	2700	N	2465.1	Pass
Time at Peak Abdomen Force	10.0	12.3	ms	10.85	Pass
Resistive Probe Force	4000	4800	N	4576.9	Pass
Time at Peak Resistive Force	10.6	13.0	ms	11.25	Pass

Channel	Manufacturer	Serial	Calibration	Calibration
		Number	Date	Due Date
Pendulum Accelerometer	ENDEVCO 7264C	T25885	2/2/2021	2/2/2022
Front Abdomen Load Cell	DENTON 2631J	LC-1524	3/19/2020	3/19/2021
Middle Abdomen Load Cell	DENTON 2631J	LC-1523	3/19/2020	3/19/2021
Rear Abdomen Load Cell	DENTON 2631J	LC-1530	3/19/2020	3/19/2021









## Certification Report ES-2re Spine Flexion - CFR 572


ATD Manufacturer	FTSS	Test Technician	C. Mantell
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan

## Results


Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.3	Pass
Humidity	10	70	%	21.9	Pass
Velocity	5.95	6.15	m/s	6.046	Pass
Lateral Spine Rotation	45	55	deg	51.6	Pass
Time at Maximum Rotation	39	53	ms	43.0	Pass
Time of Decay to Zero Degrees	37	57	ms	37.4	Pass
Pulse within Corridor?		-	-		

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Pendulum Accelerometer	ENDEVCO 7231CT	AC-C16503 Striker	2/5/2021	2/5/2022
Pendulum "A" Potentiomete	SP22G	DS-094	8/18/2020	8/18/2021
Condyle "B" Potentiometer	SP22G	DS-095	8/18/2020	8/18/2021












## Certification Report ES-2re Pelvis Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	F034	Laboratory Supervisor	K. Brogan


## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	26.0	Pass
Velocity	4.2	4.4	m/s	4.38	Pass
Resistive Force	4700	5400	N	5080.1	Pass
Time at Peak Resistive Force	11.8	16.1	ms	12.55	Pass
Pubic Force	-1590	-1230	N	-1432.2	Pass
Time at Peak Pubic Force	12.2	17.0	ms	13.40	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Pendulum Accelerometer	ENDEVCO 7264C2	T25885	2/2/2021	2/2/2022
Pubic Load Cell	Denton 3096JFL	30960459GFE	3/19/2020	3/19/2021







# **CALIBRATION TEST RESULTS**

# POST-TEST

# SID-IIS 5TH PERCENTILE FEMALE - PASSENGER ATD


SERIAL No: 300




## External Measurements - SID-IIs

Technician: K. Brogan Date: 02/05/2021

Dummy Serial Number: 300





Symbol	Description		ication m)	Result (mm)	Pass/Fail
A	Sitting Height	772	788	781	Pass
В	Shoulder Pivot Height	437	453	445	Pass
С	H-point Height	79	89	85	Pass
D	H-point from seatback	141	151	145	Pass
E	Shoulder Pivot from Backline	97	107	103	Pass
F	Thigh Clearance	119	135	126	Pass
G	Head Breadth	140	148	144	Pass
Н	Head Back from Backline	40	46	43	Pass
1	Head Depth	178	188	186	Pass
J	Head Circumference	541	551	544	Pass
K	Buttock to Knee Length	514	540	532	Pass
L	Popliteal Height	343	369	361	Pass
M	Knee Pivot to floor height	392	409	398	Pass
N	Buttock Popliteal Length	416	442	430	Pass
0	Chest Depth w/o jacket	195	211	208	Pass
Р	Foot Length	216	232	220	Pass
Q	Hip Breadth (w/pelvic plugs)	313	323	317	Pass
R	Arm Length	249	259	254	Pass
S	Knee Joint to seatback	477	493	484	Pass
V	Shoulder Width	341	357	352	Pass
W	Foot Width	78	94	83	Pass
Υ	Chest Circumference w/jacket	851	881	875	Pass
Z	Waist Circumference	761	791	773	Pass




## Certification Report SID-IIs Lateral Head Drop Left- CFR 572

ATD Manufacturer	FTSS	Test Technician	E. Helenbrook
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.9	Pass
Humidity	10	70	%	23.2	Pass
Resultant Acceleration	115	137	g's	123.2	Pass
Oscillation	0	15	%	1.6	Pass
Fore-Aft Acceleration	-15	15	g's	5.6	Pass

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
X Accelerometer	ENDEVCO 7264CT	AC-P59018	11/10/2020	5/11/2021
Y Accelerometer	ENDEVCO 7264	AC-P79189	11/10/2020	5/11/2021
Z Accelerometer	ENDEVCO 7264CT	AC-P58777	11/10/2020	5/11/2021










## Certification Report SID-IIs Neck Flexion Left- CFR 572

ATD Manufacturer	FTSS	Test Technician	E. Helenbrook
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	21.8	Pass
Humidity	10	70	%	22.3	Pass
Velocity	5.51	5.63	m/s	5.584	Pass
Pendulum Impulse at 10ms	2.2	2.8	m/s	2.32	Pass
Pendulum Impulse at 15ms	3.3	4.1	m/s	3.53	Pass
Pendulum Impulse at 20ms	4.4	5.4	m/s	4.71	Pass
Pendulum Impulse at 25ms	5.4	6.1	m/s	5.58	Pass
Pendulum Impulse from 25 to 100ms	5.5	6.2	m/s	5.85	Pass
Neck Rotation	71	81	deg	73.8	Pass
Time at Maximum Rotation	50	70	ms	60.0	Pass
Moment about the OC	36	44	Nm	43.9	Pass
Moment Decay to 0 Nm	102	126	ms	110.9	Pass

Channel	Manufacturer	Serial	Calibration	Calibration
		Number	Date	Due Date
Pendulum Accelerometer	ENDEVCO 7231CT	AC-C16503 Striker	2/5/2021	2/5/2022
Pendulum Potentiometer	Denton 78051-342	DS-184Pend	11/6/2020	11/6/2021
Condyle Potentiometer	Denton 78051-342	DS-185Pend	11/6/2020	11/6/2021
Upper Neck Load Cell	Denton 1716	17162019 FY	3/18/2020	3/18/2021










# Certification Report SID-IIs Shoulder Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	D. Reinhard
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


## Results


Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	26	Pass
Velocity	4.2	4.4	m/s	4.31	Pass
Probe Acceleration	13	18	g's	15.1	Pass
Shoulder Deflection	28	37	mm	30.9	Pass
Lateral Upper Spine Acceleration	17	22	g's	20.7	Pass

Channel	Manufacturer	Serial	Calibration	Calibration
		Number	Date	Due Date
Pendulum Accelerometer	ENDEVCO 7264C	T25885	2/2/2021	2/2/2022
Shoulder Potentiometer	Servo 08CT1-3725	DS-053 GFE	11/10/2020	5/11/2021
Upper Spine Y Accelerometer	ENDEVCO 7264CT	AC-P71281	11/9/2020	5/10/2021












## Certification Report SID-IIs Thorax With Arm Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	24.0	Pass
Velocity	6.6	6.8	m/s	6.74	Pass
Probe Acceleration after 5 ms	30	36	g's	33.0	Pass
Lateral Upper Spine Acceleration	34	43	g's	39.4	Pass
Lateral Lower Spine Acceleration	29	37	g's	32.9	Pass
Shoulder Deflection	31	40	mm	33.7	Pass
Upper Thorax Rib Deflection	25	32	mm	26.1	Pass
Mid Thorax Rib Deflection	30	36	mm	31.5	Pass
Lower Thorax Rib Deflection	32	38	mm	33.5	Pass


Channel	Manufacturer	Serial	Calibration	Calibration
		Number	Date	Due Date
Pendulum Accelerometer	ENDEVCO 7264C	T25885	2/2/2021	2/2/2022
Upper Spine T1 Y Accelerometer	ENDEVCO 7264CT	AC-P71281	11/9/2020	5/10/2021
Upper Spine T12 Y Accelerometer	ENDEVCO 7264	AC-P64147	11/9/2020	5/10/2021
Shoulder Potentiometer	Servo 08CT1-3725	DS-053 GFE	11/10/2020	5/11/2021
Upper Thorax Rib Potentiometer	Servo 08CT1-3725	DS-451GFE	11/10/2020	5/11/2021
Middle Thorax Rib Potentiometer	Servo 08TC1-3745	DS-040GFE	11/10/2020	5/11/2021
Lower Thorax Rib Potentiometer	Servo 08TC1-3725	DS-1156GFE	11/9/2020	5/10/2021














## Certification Report SID-IIs Thorax Without Arm Impact - CFR 572

ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	300	Laboratory Supervisor	K. Brogan


## Results

Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	24	Pass
Velocity	4.2	4.4	m/s	4.38	Pass
Probe Acceleration	14	18	g's	15.8	Pass
Lateral Upper Spine Acceleration	13	17	g's	16.0	Pass
Lateral Lower Spine Acceleration	7	11	g's	10.1	Pass
Upper Thorax Rib Deflection	32	40	mm	33.6	Pass
Middle Thorax Rib Deflection	39	45	mm	40.6	Pass
Lower Thorax Rib Deflection	35	43	mm	38.4	Pass


Channel	Manufacturer	Serial	Calibration	Calibration
		Number	Date	Due Date
Pendulum Accelerometer	ENDEVCO 7264C	T25885	2/2/2021	2/2/2022
Upper Spine Y Accelerometer	ENDEVCO 7264CT	AC-P71281	11/9/2020	5/10/2021
Lower Spine Y Accelerometer	ENDEVCO 7264	AC-P64147	11/9/2020	5/10/2021
Upper Thorax Rib Potentiometer	Servo 08CT1-3725	DS-451GFE	11/10/2020	5/11/2021
Middle Thorax Rib Potentiometer	Servo 08TC1-3745	DS-040GFE	11/10/2020	5/11/2021
Lower Thorax Rib Potentiometer	Servo 08TC1-3725	DS-1156GFE	11/9/2020	5/10/2021













# Certification Report SID-IIs Abdommen Impact - CFR 572


ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	300	Laboratory Supervisor	K. Brogan

# Results


Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	26.0	Pass
Velocity	4.2	4.4	m/s	4.33	Pass
Probe Acceleration	12	16	g's	13.7	Pass
Lateral Lower Spine Acceleration	9	14	g's	11.3	Pass
Upper Abdomen Rib Deflection	36	47	mm	41.1	Pass
Lower Abdomen Rib Deflection	33	44	mm	41.0	Pass

# **Transducer Calibrations**


Channel	Manufacturer	Serial	Calibration	Calibration
		Number	Date	Due Date
Probe Accelerometer EN	DEVCO 7264C-2K-T	Z2 T25885	2/2/2021	2/2/2022
Lower Spine Y Accelerometer	ENDEVCO 7264	AC-P64147	11/9/2020	5/10/2021
Upper Abdomen Rib Potentiometer	Servo 08CT1-3725	DS-308GFE	11/10/2020	5/11/2021
Lower Abdomen Rib Potentiometer	Servo 08CT1-3725	DS-307GFE	11/10/2020	5/11/2021











# Certification Report SID-IIs Acetabulum Impact - CFR 572


ATD Manufacturer	FTSS	Test Technician	D.Reinhard
ATD Serial Number	300	Laboratory Supervisor	K. Brogan

# Results


Test Parameter	Minimum Specification	Maximum Specification	Unit	Result	Pass/Fail
Temperature	20.6	22.2	°C	20.6	Pass
Humidity	10	70	%	26	Pass
Velocity	6.6	6.8	m/s	6.68	Pass
Probe Acceleration	38	47	g's	42.0	Pass
Lateral Pelvis Acceleration after 6ms	34	42	g's	40.8	Pass
Acetabulum Force	3600	4300	N	4053.6	Pass

# **Transducer Calibrations**

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Pendulum Accelerometer	ENDEVCO 7264C	T25885	2/2/2021	2/2/2022
Pelvis Y Accelerometer	ENDEVCO 7264C	AC-P51731	11/9/2020	5/10/2021
Acetabulum Load Cell	Denton IF-520	LC-236Fy	3/18/2020	3/18/2021
Certification Plug	Humanetics	14133	6/28/2020	N/A
Crash Test Plug	Humanetics	13696	9/26/2019	N/A









# SID-IIs Pelvis Plug Certification Test Plug S/N 13699

Force (-N) vs Extension (-mm)

Test Number 11347 Report Number 11385

Test Date 9/26/2019 1:57:14 PM

Testing Machine STM-20 596554; Load Cell S/N (FI360947), Units (LBS		Force @ 3.0 mm (N)	Force @ 1.5 mm (N)	Force @ 0.5 mm (N)	
-20 5965542 Units (LBS 1000	3 v	1,587.92	1,283.32	288.78	Test Results
000	,	1,361.00	850.00 1 306 00	50.00	Spec Min
		1,673.00	1,400.00	600.00	Spec Max

Crosshead Speed ( mm / min ) or Rat 12.7

Extension or Position Measured by XHD\_100 ( XHD100 )

-0.50 0.00

0.50

1.00

1.50

2.00


2.50

3.00

3.50

4.00

-200.0



Date : 1/24/2019

Part Number 180-4450

Operator

Tel 310-694-2082 FAX

SACO Research 41735 Elm St, #401 Murrieta, CA 92562

Template No 107 SACO Research

26-Sep-19



# SID-IIs Pelvis Plug Certification Test Plug S/N 13696

Report Number 11382 Test Number 11344 Test Date 9/26/2019 1:52:28 PM

_							_	-	
Testing Machine STM-20 5965542 Load Cell S/N (Fl360947), Units (LBS 1000	7				Force @ 3.0 mm (N)	orce @ 2.5 mm (N)	Force @ 1.5 mm (N)	orce @ 0.5 mm (N)	
-20 5965542 Units (LBS 10					1,597.56	1,563.70	1,316.82	304.67	Test Results
00				-	1,361.00	1,306.00	850.00	50.00	Spec Min
		E.			1,673.00	1,618.00	1,400.00	600.00	Spec Max
200.0 -	400.0 -	600.0 -	800.0 -	1000.0 -		1200.0 -		1400.0 -	1600.0 -
		1	/						
		\							

SACO Research Template No 107

26-Sep-19

SACO Research 41735 Elm St, #401 Murrieta, CA 92562

Date: 9/36/2019

Part Number 180-4450

Operator

Tel 310-694-2082 FAX

Notes:

Crosshead Speed (mm / min) or Rat 12.7
Extension or Position Measured by XHD\_100 (XHD100)

-0.50

0.00

0.50

1.00

1.50


2.00

2.50

3.00


3.50 4.00

-200.0



Force (-N) vs Extension (-mm)

C-90





# Certification Report SID-IIs Iliac Impact - CFR 572


ATD Manufacturer	FTSS	Test Technician	K. Brogan
ATD Serial Number	300	Laboratory Supervisor	D.Reinhard

### Results


Test Parameter	Minimum Maximun Specification Specificati		Unit	Result	Pass/Fail	
Temperature	20.6	22.2	°C	20.6	Pass	
Humidity	10	70	%	25.0	Pass	
Velocity	4.2	4.4	m/s	4.26	Pass	
Probe Acceleration	36	45	g's	41.9	Pass	
Lateral Pelvis Acceleration	28	39	g's	34.4	Pass	
Iliac Force	4100	5100	N	5024.4	Pass	

# **Transducer Calibrations**

Channel	Manufacturer	Serial Number	Calibration Date	Calibration Due Date
Pendulum Accelerometer	ENDEVCO 7264C	T25885	2/2/2021	2/2/2022
Pelvis Y Accelerometer	ENDEVCO 7264C	AC-P51731	11/9/2020	5/10/2021
Iliac Load Cell	DENTON 3228J	LC-279Fy	11/23/2020	11/23/2021







# **APPENDIX D**

# TEST EQUIPMENT AND INSTRUMENTATION CALIBRATION DATA

Table 1 – Dummy Instrumentation (ES-2re)

			ES-2re S/N: F034			
_			Serial Number	Manufacturer	Calibration Date	
		Χ	P51884	Endevco	9/22/2020	
	Primary	Υ	P73161	Endevco	9/22/2020	
Hood Appleremeters		Z	P79588	Endevco	9/22/2020	
Head Accelerometers		Х	P74963	Endevco	9/22/2020	
	Redundant	Υ	P58864	Endevco	9/22/2020	
		Z	AC-P52030	Endevco	11/13/2020	
Thorax Rib	Upper	Υ	DS-183GFE	Honeywell	10/8/2020	
Displacement	Middle	Υ	DS-184GFE	Honeywell	10/8/2020	
Potentiometers	Lower	Υ	DS-182GFE	Honeywell	10/8/2020	
	Forward	Υ	LC-1524	Denton	3/19/2020	
Abdomen Load Cells	Middle	Υ	LC-1523	Denton	3/19/2020	
	Rear	Υ	LC-1530	Denton	3/19/2020	
Lower Spine Accelerometers (T12)		Х	P52981	Endevco	9/22/2020	
		Υ	P82183	Endevco	9/18/2020	
		Z	P51986	Endevco	9/22/2020	
Pubic Symphysis L	oad Cell	Υ	30960459GFE	Denton	3/19/2020	

Table 2 – Dummy Instrumentation (SID-IIs)

, in the second			SID-IIs S/N: 300			
				Serial Number	Manufacturer	Calibration Date
Head Accelerometers		Primary	X	AC-P59018	ENDEVCO	11/10/2020
			Υ	AC-P79189	ENDEVCO	11/10/2020
			Z	AC-P58777	ENDEVCO	11/10/2020
		Redundant	Χ	AC-P68057	ENDEVCO	11/10/2020
			Υ	AC-P58986	ENDEVCO	11/10/2020
			Z	AC-P52025	ENDEVCO	11/10/2020
	Thoracic Rib	Upper	Υ	DS-451GFE	Servo	11/10/2020
Displacement Potentiometers		Middle	Υ	DS-040GFE	Servo	11/10/2020
		Lower	Υ	DS-1156GFE	Servo	11/9/2020
	Abdominal Rib	Upper	Υ	DS-308GFE	Servo	11/10/2020
		Lower	Υ	DS-307GFE	Servo	11/10/2020
•			Х	AC-P64003	ENDEVCO	11/9/2020
Lower Spine Accelerometers (T12)			Υ	AC-P64147	ENDEVCO	11/9/2020
			Z	AC-P58786	ENDEVCO	11/9/2020
Acetabulum Load Cell			Υ	LC-236Fy	DENTON	3/18/2020
Iliac Wing Load Cell			Υ	LC-279Fy	DENTON	11/23/2020
Pelvis Plug (struck side)				13407	SACO	5/20/2020
Pelvis Plug (non-struck side)				13018	SACO	7/30/2019

Table 3 – Vehicle Instrumentation

Vehicle Instrumentation			Serial Number	Manufacturer	Calibration Date
1	Vehicle Center of Gravity		1201-1000_A374278	Measurement Specialties	12/1/2020
	Vehicle Center of Gravity		1201-1000_A374285	Measurement Specialties	12/1/2020
	Vehicle Center of Gravity		1201-1000_A374292	Measurement Specialties	12/1/2020
	Right Sill at Front Seat		1201-1000_A372808	Measurement Specialties	11/19/2020
2	Right Sill at Front Seat		1201-1000_A372815	Measurement Specialties	11/19/2020
	Right Sill at Front Seat	Z	1201-1000_A372817	Measurement Specialties	11/19/2020
	Right Sill at Rear Seat		1201-1000_A372842	Measurement Specialties	11/20/2020
3	Right Sill at Rear Seat		1201-1000_A372843	Measurement Specialties	11/20/2020
	Right Sill at Rear Seat	Z	1201-1000_A372859	Measurement Specialties	11/20/2020
4	Left Sill at Front Door	Υ	1201-1000_A315901	Measurement Specialties	1/18/2021
5	Left Sill at Rear Door	Υ	1201-1000_A280391	Measurement Specialties	9/1/2020
6	Left A-Post Lower		1201-1000_A351017	Measurement Specialties	12/5/2020
7	Left A-Post Middle		1201-1000_A315760	Measurement Specialties	1/18/2021
8	Left B-Post Lower		1201-1000_A222645	Measurement Specialties	10/10/2020
9	Left B-Post Middle		1201-1000_A280852	Measurement Specialties	10/3/2020
10	Front Seat Track	Υ	1201-1000_A315970	Measurement Specialties	10/10/2020
11	Rear Seat Track or Structure	Υ	1201-1000_A280993	Measurement Specialties	10/10/2020
12	Right Rear Occ. Compartment	Υ	1201-1000_A315124	Measurement Specialties	10/10/2020
13	Engine Block		1201-1000_A290922	Measurement Specialties	10/5/2020
13	Engine Block	Υ	1201-1000_A300208	Measurement Specialties	10/5/2020
	Rear Floorpan Above Axle		1201-1000_A250364	Measurement Specialties	1/18/2021
14	Rear Floorpan Above Axle		1201-1000_A255841	Measurement Specialties	1/18/2021
	Rear Floorpan Above Axle	Z	1201-1000_A335453	Measurement Specialties	1/18/2021

**TABLE 4 – MDB Instrumentation** 

MDB Instrumentation	Serial Number	Manufacturer	Calibration Date	
MDB Center of Gravity	Χ	1201-1000_A315181	Measurement Specialties	10/6/2020
MDB Center of Gravity		1201-1000_A315931	Measurement Specialties	10/7/2020
MDB Center of Gravity	Z	1201-1000_A315085	Measurement Specialties	10/6/2020
Left Frame at Rear Axle Centerline	Χ	1201-1000_A315983	Measurement Specialties	10/5/2020