# Part 573 Safety Recall Report

Manufacturer Name :Forest River, Inc.Submission Date :JUL 06, 2022NHTSA Recall No. :22V-476Manufacturer Recall No. :700-1530

## Manufacturer Information :

Manufacturer Name : Forest River, Inc. Address : 55470 CR 1 P.O. Box 3030 Elkhart IN 46515-3030 Company phone : 1-800-348-7440

## Vehicle Information :

Vehicle 1:2021-2022 Forest River Inc. Cargo Mate Cargo TrailerVehicle Type :TRAILERSBody Style :OTHERPower Train :NRDescriptive Information :All units built since inception of these models are include2021CARGO MATEZ021CARGO MATEZ022CARGO MATEZ022CARGO MATEZ022CARGO MATEZ022CARGO MATEZ022CARGO MATEZ022CARGO MATEZ022CARGO MATEZ022CARGO MATEZ023CARGO MATEZ024CARGO MATEZ025CARGO MATEZ026CARGO MATEZ027CARGO MATEZ028CARGO MATEZ029CARGO MATEZ020CARGO MATEZ021CARGO MATEZ022CARGO MATEZ023CARGO MATEZ024CARGO MATEZ025CARGO MATEZ026CARGO MATEZ027CARGO MATEZ028CARGO MATEZ029CARGO MATEZ020CARGO MATEZ021CARGO MATEZ022CARGO MATEZ023CARGO MATEZ034CARGOZ035CARGOZ036CARGOZ037CARGOZ037CARGOZ037CARGOZ037CARGOZ037CARGOZ037CARGOZ037CARGOZ037CARGOZ037CARGO	d in the recall.
Vehicle Type :TRAILERS Body Style :Body Style :OTHER Power Train :Power Train :NRDescriptive Information :All units built since inception of these models are include 2021 CARGO MATE TXNN714TA3 5 2021 CARGO MATE TXNN716TA3 67 2022 CARGO MATE TXNN714TA3 95	d in the recall.
Power Train :NRDescriptive Information :All units built since inception of these models are include 2021 CARGO MATE TXNN714TA3 5 2021 CARGO MATE TXNN716TA3 67 2022 CARGO MATE TXNN714TA3 95	d in the recall.
Descriptive Information :All units built since inception of these models are include2021CARGO MATETXNN714TA32021CARGO MATETXNN716TA32022CARGO MATETXNN714TA3	d in the recall.
2021CARGO MATE TXNN714TA3 52021CARGO MATE TXNN716TA3 672022CARGO MATE TXNN714TA3 95	d in the recall.
GRAND TOTAL 324	
Production Dates : JUN 25, 2020 - MAY 06, 2022	
VIN Range 1 : Begin : NR End : NR	Not sequential
Vehicle 2:2021-2022 Forest River Inc. Continental Cargo TrailersVehicle Type :TRAILERSBody Style :OTHERPower Train :NRDescriptive Information :All units built since inception of these models are include2021CONTINENTAL CARGOTXVA714TA32120212021CONTINENTAL CARGOTXVA716TA39320222022CONTINENTAL CARGOTXVA716TA3932022CONTINENTAL CARGOTXVA716TA31182022CONTINENTAL CARGOTXVA716TA3402GRAND TOTAL634	d in the recall.
Production Dates : JUN 22, 2020 - MAY 06, 2022	
VIN Range 1 : Begin : NR End : NR	☐ Not sequential



Number of potentially involved : 958 Estimated percentage with defect : 100 %

**Population :** 

22V-476

#### **Description of Defect :**

Description of the Defect :	The safety chains do not meet the Gross Vehicle Weight Rating and could potentially break
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	If the unit was to detach from the hitch the safety chains may not be sufficient to hold the unit increasing the risk of a crash.
Description of the Cause :	When the model was created it was built off of an existing model. Existing model only has a single axle, this model is the tandems version. Safety chains were not checked to ensure they matched the GVWR with the additional axle
Identification of Any Warning that can Occur :	

#### **Involved Components :**

Component Name 1: Safety Chains

Component Description : Safety Chains

Component Part Number: N/A

### **Supplier Identification :**

#### **Component Manufacturer**

Name : NR Address : NR NR

Country: NR

#### Chronology :

On 6/27/2022, during a Corporate Quality Manager inspection of the plant it was discovered the safety chains were under rated for the GVWR of the vehicle. The safety chains on the vehicle are rated at 7600 lbs. and should be 11,700 lbs.

On 7/1/2022, Forest Rivers Corporate Recall Committee voted to recall

The information contained in this report was submitted pursuant to 49 CFR §573

<b>Description of Remedy</b> :	
Description of Remedy Program :	Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River Dealer or Service Center will need to replace the under rated safety chains with properly rated safety chains for the GVWR of the vehicle.
	What is the Forest River Customer Service Phone Number? (254) 420-0171
	If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:
	Cargo (Texas) Forest River, Inc.
	Attn: WARRANTY MANAGER 8300 Imperial Dr. Waco, TX 76712
	Recalled Component Safety Chain 7600 lb. Replacement Safety Chain is 11,700 lb.
from kecaned component.	The safety chains will now meet the GVWR of the vehicle
	The concern was immediately corrected by installing the correct rated chains for the unit at the time of the inspection on $6/27/2022$ .
Recall Schedule :	
Description of Recall Schedule : Planned Dealer Notification Date :	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter. AUG 15, 2022 - AUG 15, 2022
- minica Doutor Rothication Date .	

\* NR - Not Reported

Planned Owner Notification Date : AUG 15, 2022 - AUG 15, 2022

The information contained in this report was submitted pursuant to 49 CFR §573