

Compliance Testing of Rear Impact Guards to FMVSS No. 223

ACTIVE

Contract Opportunity

Notice ID

693JJ923R000094

Related Notice

693JJ923R000094

Contract Line Item Number

Department/Ind. Agency

TRANSPORTATION, DEPARTMENT OF

Sub-tier

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Office

693JJ9 NHTSA OFFICE OF ACQUISITION

Award Details

- **Contract Award Date:** May 22, 2023
- **Contract Award Number:** 693JJ923D000046
- **Task/Delivery Order Number:**
- **Contractor Awarded Unique Entity ID:** EPH2KZN9MLB6
- **Contractor Awarded Name:** Applus Idiada Karco Engineering, LLC
- **Contractor Awarded Address:** Adelanto, CA 92301-3954 USA
- **Base and All Options Value (Total Contract Value):** \$2,079,800.00

General Information

- **Contract Opportunity Type:** Award Notice (Original)
- **All Dates/Times are:** (UTC-04:00) EASTERN STANDARD TIME, NEW YORK, USA
- **Original Published Date:** May 23, 2023 12:32 pm EDT
- **Inactive Policy:** 15 days after contract award date
- **Original Inactive Date:** Jun 06, 2023
- **Initiative:**
 - None

Classification

- **Original Set Aside:**

- **Product Service Code:** H223 - EQUIPMENT AND MATERIALS TESTING-GROUND EFFECT VEHICLES, MOTOR VEHICLES, TRAILERS, AND CYCLES
- **NAICS Code:**
 - 541380 - Testing Laboratories and Services
- **Place of Performance:**

Description

1.
 1. services under this contract are necessary to support NHTSA's determination whether a rear impact guard complies with the applicable requirements of FMVSS No. 223, Rear Impact Guards, see 49 C.F.R. §571.223.
 2. Contractor shall furnish the necessary qualified technical personnel, facilities, materials, equipment, and services to perform the procurement, receipt, inventory, inspection, testing, reporting, storage and disposal of rear impact guards provided to the Contractor as Government Furnished Test Items (GFTI) or purchased by the Contractor as Contractor Purchased Test Items (CPTI).
 3. Contractor shall provide additional information specific to the tests conducted for NHTSA upon request and to support a non-compliance investigation opened by NHTSA based upon a test performed by the Contractor. This may include, but is not limited to test data, photos, video, details about the test set up, test observations, details about the test item configuration.

Attachments/Links

No attachments or links have been added to this opportunity.

Contact Information

Contracting Office Address

- OFFICE OF ACQUISITION MANAGEMENT 1200 NEW JERSEY AVE SE, ROOM W51-30
- WASHINGTON , DC 20590
- USA

Primary Point of Contact

- **Danna Brooks**
- danna.brooks@dot.gov

Secondary Point of Contact

- **Reba Dyer**
- Reba.Dyer@dot.gov