

Part 573 Safety Recall Report

22T-011

Manufacturer Name : PREMIORI LLC**Submission Date :** OCT 27, 2022**NHTSA Recall No. :** 22T-011**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : PREMIORI LLC

Address : Levanevskogo street 91
10903 NW 122nd ST, Medley,
FLORIDA Bila Tserkva, Kyiv region 00
09100

Company phone : (305)663-3508

Population :

Number of potentially involved : 8

Estimated percentage with defect : 1 %

Tire Information :

Tire Brand 1 : PREMIORRI

Tire Line : Solazo

Tire Size : 175/65R14 82H

Descriptive Information : The tires lacked the full DOT symbol on one sidewall

Production Dates : FEB 07, 2021 - APR 30, 2021

TIN (Tire Identification Number)

Plant ID	Size code	Optional Code	Begin M Code	End M Code
KC	F1	NR	08	21

Description of Noncompliance :

Description of the Noncompliance : The tires lacked the DOT symbol and full or partial tire identification number on one sidewall

FMVSS 1 : 139 - New pneumatic radial tires for light vehicles

FMVSS 2 : NR

Description of the Safety Risk : This noncompliance does not relate to motor vehicle safety

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name : tire sidewall markings

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : PREMIORI LLC

Address : Levanevskogo street, 91 building

10903 NW 122nd ST, Medley, FLORIDA Bila Tserkva Foreign States 09100

Country : Ukraine

Chronology :

This noncompliance became known upon receipt of a request from the US Department of Transportation
We found one mold of this size of tires
We have corrected this noncompliance
After investigating the reasons for this noncompliance and consulting with the technical service, it was concluded that this did not affect the safety of vehicles

Description of Remedy :

Description of Remedy Program : We corrected all the tires in our possession and destroyed at in our possession dealers

How Remedy Component Differs from Recalled Component : tire sidewall markings

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : We state that we do not feel it posses a safety risk to owners so we will not be mailing to owners pending NHTSA's review

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

* NR - Not Reported