OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24V-105

Manufacturer Name: Belmont Trailers LLC

Submission Date: FEB 13, 2024 NHTSA Recall No.: 24V-105 Manufacturer Recall No.: NR NHTSA

NATIONAL HIGHWAY TRAFFIC
SAFETY ADMINISTRATION

Manufacturer Information:

Manufacturer Name: Belmont Trailers LLC

Address: 40 Hess Road

Leola PA 17540

Company phone: 5560040

Population:

Number of potentially involved : 56 Estimated percentage with defect : 90%

Vehicle Information:

Vehicle 1: 2023-2024 Belmont Trailers FlatTrak

Vehicle Type: TRAILERS Body Style: OTHER Power Train: NR

Descriptive Information: Spindle Mount Issue

Production Dates: SEP 01, 2022 - FEB 09, 2024

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: Spindle Mount Issue

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Spindle Mount can become cracked and separate from the arm

Description of the Cause: NR
Identification of Any Warning NR
that can Occur:

Involved Components:

Component Name 1: NR
Component Description: NR
Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: Belmont Trailers Address: 40 Hess Road

Leola Pennsylvania 17540

Country: United States

Chronology:

When first cracks were discovered, we made some calls to get some local trailers back to evaluate. We decided to do a complete recall when there was more than one trailer with the defect.

Description of Remedy:

Description of Remedy Program: Belmont will assist in locating a reputable place to have the spindles

grinded out and re-welded. This will be at no charge to the customer.

How Remedy Component Differs NR

from Recalled Component :

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date: FEB 19, 2024 - MAR 19, 2024 Planned Owner Notification Date: FEB 19, 2024 - MAR 19, 2024

^{*} NR - Not Reported