

Part 573 Safety Recall Report

24E-062

Manufacturer Name : Dongguan Biaoming technology Co., Ltd.**Submission Date :** JUL 20, 2024**NHTSA Recall No. :** 24E-062**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :****Manufacturer Name :** Dongguan Biaoming technology Co., Ltd.**Number of potentially involved :** 24**Address :** #401, No. 18, Gangxia Nan Street**Estimated percentage with defect :** 58 %**Changgang Zhen Dongguan 00 523106****Company phone :** 13645109187**Equipment Information :****Brand / Trade 1 :** No brand**Model :** Tesla to CCS1/CCS2**Part No. :** Jeco041**Size :** NR**Function :** NR**Descriptive Information :** Does not work, unable to charge.**Production Dates :** APR 08, 2024 - APR 23, 2024**Description of Defect :****Description of the Defect :** Lack of communication potocol**FMVSS 1 :** NR**FMVSS 2 :** NR**Description of the Safety Risk :** Does not work, unable to charge.**Description of the Cause :** NR**Identification of Any Warning** NR
that can Occur :**Involved Components :**

Component Name : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Dongguan Biaoming technology Co., Ltd.

Address : #204, 27 Huaibei Road, Humen Town
Dongguan Foreign States 523900

Country : China

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

* NR - Not Reported