OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24V-833

Manufacturer Name: Kawasaki Motors Corp., U.S.A.

Submission Date: NOV 05, 2024 **NHTSA Recall No.:** 24V-833

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Kawasaki Motors Corp., U.S.A.

Address: PO Box 25252

Santa Ana CA 92799-5252

Company phone: 949-770-0400

Population:

Number of potentially involved: 299 Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2024-2024 Kawasaki Motors, Ltd. Z7 Hybrid ABS and Ninja® 7 Hybrid ABS

Vehicle Type: MOTORCYCLES

Body Style: OTHER

Power Train: HYBRID ELECTRIC

Descriptive Information: The affected vehicles containing the problem are certain 2024 Z7 Hybrid ABS - 199 /

Ninja® 7 Hybrid ABS - 100 models. The recall population was determined by the

beginning and ending production date for the models affected.

Production Dates: MAR 05, 2024 - APR 01, 2024

VIN Range 2: Begin: ML5CRGA12RDA02449 End: ML5CRGA12RDA03438

☐ Not sequential

Description of Defect:

Description of the Defect: On certain eligible units, the head pipe was not properly welded to the frame.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The weld of the head pipe to the frame can crack and negatively affect vehicle

handling.

Description of the Cause: Improper welding.

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: NR
Component Description: NR
Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: Kawasaki Motors Ltd. Address: 1-1, Kawasaki-cho

Akashi, Hyogo Foreign States 673-8666

Country: Japan

Chronology:

NR

Description of Remedy:

Description of Remedy Program : NR How Remedy Component Differs NR from Recalled Component :

Identify How/When Recall Condition NR was Corrected in Production :

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

^{*} NR - Not Reported