OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24V-888

Manufacturer Name: Braun Corporation **Submission Date:** NOV 25, 2024

NHTSA Recall No.: 24V-888 Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Braun Corporation

Address: 631 West 11 Street

Winamac IN 46996

Company phone: 1-800-488-0359

Population:

Number of potentially involved : 44 Estimated percentage with defect : 50 %

Vehicle Information :				
VIN Range 1 : Begin :	2C4RC1BG1NR188197	End:	2C4RC1BG1NR188197	✓ Not sequential
VIN Range 2: Begin:	2C4RC1BG2NR218310	End:	2C4RC1BG2NR218310	■ Not sequential
VIN Range 3: Begin:	2C4RC1BG1NR188197	End:	2C4RC1BG1NR188197	✓ Not sequential
VIN Range 4: Begin:	2C4RC1BG2NR218310	End:	2C4RC1BG2NR218310	■ Not sequential
VIN Range 5: Begin:	2C4RC1BG4NR190493	End:	2C4RC1BG4NR190493	■ Not sequential
VIN Range 6: Begin:	2C4RC1BG9NR186245	End:	2C4RC1BG9NR186245	■ Not sequential
VIN Range 7 : Begin :	2C4RC1CG0PR588219	End:	2C4RC1CG0PR588219	■ Not sequential
VIN Range 8 : Begin :	2C4RC1CG0PR591721	End:	2C4RC1CG0PR591721	■ Not sequential
VIN Range 9: Begin:	2C4RC1CG0PR603009	End:	2C4RC1CG0PR603009	■ Not sequential
VIN Range 10: Begin:	2C4RC1CG0PR603012	End:	2C4RC1CG0PR603012	■ Not sequential
VIN Range 11 : Begin :	2C4RC1CG1PR587869	End:	2C4RC1CG1PR587869	■ Not sequential
VIN Range 12 : Begin :	2C4RC1CG1PR588147	End:	2C4RC1CG1PR588147	■ Not sequential
VIN Range 13: Begin:	2C4RC1CG2PR587606	End:	2C4RC1CG2PR587606	■ Not sequential
VIN Range 14 : Begin :	2C4RC1CG4PR598042	End:	2C4RC1CG4PR598042	■ Not sequential
VIN Range 15 : Begin :	2C4RC1BG1NR188197	End:	2C4RC1BG1NR188197	✓ Not sequential
VIN Range 16: Begin:	2C4RC1BG2NR218310	End:	2C4RC1BG2NR218310	■ Not sequential
VIN Range 17 : Begin :	2C4RC1BG4NR190493	End:	2C4RC1BG4NR190493	■ Not sequential
VIN Range 18: Begin:	2C4RC1BG9NR186245	End:	2C4RC1BG9NR186245	■ Not sequential
VIN Range 19: Begin:	2C4RC1CG0PR588219	End:	2C4RC1CG0PR588219	■ Not sequential
VIN Range 20 : Begin :	2C4RC1CG0PR591721	End:	2C4RC1CG0PR591721	■ Not sequential
VIN Range 21 : Begin :	2C4RC1CG0PR603009	End:	2C4RC1CG0PR603009	■ Not sequential
VIN Range 22 : Begin :	2C4RC1CG0PR603012	End:	2C4RC1CG0PR603012	■ Not sequential
VIN Range 23 : Begin :	2C4RC1CG1PR587869	End:	2C4RC1CG1PR587869	■ Not sequential
VIN Range 24 : Begin :	2C4RC1CG1PR588147	End:	2C4RC1CG1PR588147	■ Not sequential
VIN Range 25 : Begin :	2C4RC1CG2PR587606	End:	2C4RC1CG2PR587606	■ Not sequential
VIN Range 26 : Begin :	2C4RC1CG4PR598042	End:	2C4RC1CG4PR598042	■ Not sequential
VIN Range 27 : Begin :	2C4RC1BG5RR180626	End:	2C4RC1BG5RR180626	■ Not sequential
VIN Range 28 : Begin :	2C4RC1FG2RR191383	End:	2C4RC1FG2RR191383	■ Not sequential
VIN Range 29 : Begin :	2C4RC1FG4RR191384	End:	2C4RC1FG4RR191384	■ Not sequential
VIN Range 30 : Begin :	2C4RC1FG6RR183240	End:	2C4RC1FG6RR183240	■ Not sequential
VIN Range 31 : Begin :	2C4RC1FG4RR195869	End:	2C4RC1FG4RR195869	■ Not sequential
VIN Pango 22 · Rogin ·	9CADC1ECVDD101A99	End ·	9CADC1ECVDD101A99	☐ Not sequential

VIN Range 47 : Begin :	2C4RC1CG0PR603009	End:	2C4RC1CG0PR603009	☐ Not sequential
VIN Range 48 : Begin :	2C4RC1CG0PR603012	End:	2C4RC1CG0PR603012	■ Not sequential
VIN Range 49: Begin:	2C4RC1CG1PR587869	End:	2C4RC1CG1PR587869	■ Not sequential
VIN Range 50: Begin:	2C4RC1CG1PR588147	End:	2C4RC1CG1PR588147	■ Not sequential
VIN Range 51: Begin:	2C4RC1CG2PR587606	End:	2C4RC1CG2PR587606	■ Not sequential
VIN Range 52 : Begin :	2C4RC1CG4PR598042	End:	2C4RC1CG4PR598042	■ Not sequential
VIN Range 53: Begin:	2C4RC1BG5RR180626	End:	2C4RC1BG5RR180626	■ Not sequential
VIN Range 54 : Begin :	2C4RC1FG2RR191383	End:	2C4RC1FG2RR191383	■ Not sequential
VIN Range 55 : Begin :	2C4RC1FG4RR191384	End:	2C4RC1FG4RR191384	☐ Not sequential
VIN Range 56: Begin:	2C4RC1FG6RR183240	End:	2C4RC1FG6RR183240	■ Not sequential
VIN Range 57 : Begin :	2C4RC1FG4RR195869	End:	2C4RC1FG4RR195869	☐ Not sequential
VIN Range 58 : Begin :	2C4RC1FGXRR191423	End:	2C4RC1FGXRR191423	☐ Not sequential
VIN Range 59: Begin:	2C4RC1CG0RR140906	End:	2C4RC1CG0RR140906	☐ Not sequential
VIN Range 60: Begin:	2C4RC1CG1RR169959	End:	2C4RC1CG1RR169959	☐ Not sequential
VIN Range 61 : Begin :	2C4RC1CG2RR152636	End:	2C4RC1CG2RR152636	☐ Not sequential
VIN Range 62 : Begin :	2C4RC1CG2RR152670	End:	2C4RC1CG2RR152670	☐ Not sequential
VIN Range 63: Begin:	2C4RC1CG3RR157943	End:	2C4RC1CG3RR157943	☐ Not sequential
VIN Range 64 : Begin :	2C4RC1CG5RR168278	End:	2C4RC1CG5RR168278	☐ Not sequential
VIN Range 65 : Begin :	2C4RC1CG6RR130090	End:	2C4RC1CG6RR130090	☐ Not sequential
VIN Range 66 : Begin :	2C4RC1CG6RR140893	End:	2C4RC1CG6RR140893	☐ Not sequential
VIN Range 67 : Begin :	2C4RC1CG6RR141168	End:	2C4RC1CG6RR141168	☐ Not sequential
VIN Range 68 : Begin :	2C4RC1CG6RR141171	End:	2C4RC1CG6RR141171	☐ Not sequential
VIN Range 69 : Begin :	2C4RC1CG6RR141199	End:	2C4RC1CG6RR141199	☐ Not sequential
VIN Range 70 : Begin :	2C4RC1CG7RR141213	End:	2C4RC1CG7RR141213	☐ Not sequential
VIN Range 71 : Begin :	2C4RC1CG7RR152518	End:	2C4RC1CG7RR152518	☐ Not sequential
VIN Range 72 : Begin :	2C4RC1CG7RR152647	End:	2C4RC1CG7RR152647	☐ Not sequential
VIN Range 73 : Begin :	2C4RC1CG8RR130107	End:		☐ Not sequential
VIN Range 74 : Begin :			2C4RC1CG8RR130110	☐ Not sequential
VIN Range 75 : Begin :				☐ Not sequential
VIN Range 76 : Begin :	2C4RC1CG8RR141169		2C4RC1CG8RR141169	☐ Not sequential
VIN Range 77 : Begin :	2C4RC1CG8RR141172	End:		☐ Not sequential
VIN Range 78 : Begin :	2C4RC1CG8RR155718	End:		☐ Not sequential
VIN Range 79 : Begin :	2C4RC1BG1NR188197	End:		✓ Not sequential
VIN Range 80 : Begin :	2C4RC1BG2NR218310	End:		☐ Not sequential
VIN Range 81 : Begin :	2C4RC1BG4NR190493	End:		☐ Not sequential
VIN Range 82 : Begin :	2C4RC1BG9NR186245	End:		☐ Not sequential
VIN Range 83 : Begin :	2C4RC1CG0PR588219	End:	2C4RC1CG0PR588219	☐ Not sequential
VIN Range 84: Begin:	2C4RC1CG0PR591721	End:	2C4RC1CG0PR591721	☐ Not sequential
VIN Range 85 : Begin :	2C4RC1CG0PR603009	End:	2C4RC1CG0PR603009	☐ Not sequential
VIN Range 86: Begin:	2C4RC1CG0PR603012	End:	2C4RC1CG0PR603012	☐ Not sequential
VIN Range 87 : Begin :	2C4RC1CG1PR587869	End:	2C4RC1CG1PR587869	☐ Not sequential
VIN Range 88 : Begin :	2C4RC1CG1PR588147	End:	2C4RC1CG1PR588147	☐ Not sequential
VIN Range 89 : Begin :	2C4RC1CG2PR587606	End:	2C4RC1CG2PR587606	☐ Not sequential
VIN Range 90 : Begin :	2C4RC1CG4PR598042	End:	2C4RC1CG4PR598042	☐ Not sequential
VIN Range 91 : Begin :	2C4RC1BG5RR180626	End:	2C4RC1BG5RR180626	☐ Not sequential
VIN Range 92 : Begin :	2C4RC1FG2RR191383	End:	2C4RC1FG2RR191383	☐ Not sequential —

Vehicle 1: 202	4-2024 Chrysler Voyager aı	nd Pacif	ica	
Vehicle Type :	J J O			
Body Style :				
Power Train: NR				
Descriptive Information: 11/	19/2024, discovered some	seats in	certain converted WAVs	did not have the
±	ters installed. · Determined			
wer	e found to be affected. 6 Pa	cifica a	nd 38 Voyager units.	
Production Dates: OCT	28, 2024 - NOV 19, 2024			
VIN Range 93 : Begin	1: 2C4RC1FG4RR191384	End:	2C4RC1FG4RR191384	■ Not sequential
VIN Range 94 : Begin	1: 2C4RC1FG6RR183240	End:	2C4RC1FG6RR183240	■ Not sequential
VIN Range 95 : Begin	1: 2C4RC1FG4RR195869	End:	2C4RC1FG4RR195869	■ Not sequential
VIN Range 96 : Begin	1: 2C4RC1FGXRR191423	End:	2C4RC1FGXRR191423	■ Not sequential
VIN Range 97 : Begin	1: 2C4RC1CG0RR140906	End:	2C4RC1CG0RR140906	■ Not sequential
VIN Range 98 : Begin	1: 2C4RC1CG1RR169959	End:	2C4RC1CG1RR169959	■ Not sequential
VIN Range 99 : Begin	1: 2C4RC1CG2RR152636	End:	2C4RC1CG2RR152636	■ Not sequential
VIN Range 100 : Begin	1: 2C4RC1CG2RR152670	End:	2C4RC1CG2RR152670	■ Not sequential
VIN Range 101 : Begin	1: 2C4RC1CG3RR157943	End:	2C4RC1CG3RR157943	■ Not sequential
VIN Range 102 : Begin	1: 2C4RC1CG5RR168278	End:	2C4RC1CG5RR168278	■ Not sequential
VIN Range 103 : Begin	1: 2C4RC1CG6RR130090	End:	2C4RC1CG6RR130090	■ Not sequential
VIN Range 104 : Begin	1: 2C4RC1CG6RR140893	End:	2C4RC1CG6RR140893	■ Not sequential
VIN Range 105 : Begin	1: 2C4RC1CG6RR141168	End:	2C4RC1CG6RR141168	■ Not sequential
VIN Range 106 : Begin	1: 2C4RC1CG6RR141171	End:	2C4RC1CG6RR141171	■ Not sequential
VIN Range 107 : Begin	1: 2C4RC1CG6RR141199	End:	2C4RC1CG6RR141199	■ Not sequential
VIN Range 108 : Begin	1: 2C4RC1CG7RR141213	End:	2C4RC1CG7RR141213	■ Not sequential
VIN Range 109 : Begin	1: 2C4RC1CG7RR152518	End:	2C4RC1CG7RR152518	■ Not sequential
VIN Range 110 : Begin	1: 2C4RC1CG7RR152647	End:	2C4RC1CG7RR152647	■ Not sequential
VIN Range 111 : Begin	1: 2C4RC1CG8RR130107	End:	2C4RC1CG8RR130107	■ Not sequential
VIN Range 112 : Begin	1: 2C4RC1CG8RR130110	End:	2C4RC1CG8RR130110	■ Not sequential
VIN Range 113 : Begin	1: 2C4RC1CG8RR140894	End:	2C4RC1CG8RR140894	■ Not sequential
VIN Range 114 : Begin		End:	2C4RC1CG8RR141169	■ Not sequential
VIN Range 115 : Begin		End:	2C4RC1CG8RR141172	■ Not sequential
VIN Range 116 : Begin	1: 2C4RC1CG8RR155718	End:	2C4RC1CG8RR155718	■ Not sequential
VIN Range 117 : Begin	1: 2C4RC1CG9RR140905	End:	2C4RC1CG9RR140905	■ Not sequential
VIN Range 118 : Begin		End:	2C4RC1CG9RR146882	■ Not sequential
VIN Range 119 : Begin		End:	2C4RC1CG9RR152665	■ Not sequential
VIN Range 120 : Begin		End:	2C4RC1CG9RR155727	■ Not sequential
VIN Range 121 : Begin		End:		☐ Not sequential
VIN Range 122 : Begin	1: 2C4RC1CGXRR141187	End:	2C4RC1CGXRR141187	■ Not sequential

Vehicle 2: 2024-2	024 Chrysler Pacifica			
Vehicle Type :				
Body Style :				
Power Train: NR				
Descriptive Information: · 11/19 limiters	/2024, discovered some s installed. · Determined			
Production Dates: OCT 28	, 2024 - NOV 13, 2024			
VIN Range 1 : Begin :	2C4RC1BG1NR188197	End:	2C4RC1BG1NR188197	✓ Not sequential
VIN Range 2 : Begin :	2C4RC1BG2NR218310	End:	2C4RC1BG2NR218310	☐ Not sequential
VIN Range 3: Begin:	2C4RC1BG4NR190493	End:	2C4RC1BG4NR190493	☐ Not sequential
VIN Range 4 : Begin :	2C4RC1BG9NR186245	End:	2C4RC1BG9NR186245	■ Not sequential
VIN Range 5 : Begin :	2C4RC1BG5RR180626	End:	2C4RC1BG5RR180626	■ Not sequential
VIN Range 6: Begin:	2C4RC1FG2RR191383	End:	2C4RC1FG2RR191383	☐ Not sequential
VIN Range 7 : Begin :	2C4RC1FG4RR191384	End:	2C4RC1FG4RR191384	■ Not sequential
VIN Range 8: Begin:	2C4RC1FG6RR183240	End:	2C4RC1FG6RR183240	■ Not sequential
VIN Range 9: Begin:	2C4RC1FG4RR195869	End:	2C4RC1FG4RR195869	■ Not sequential
VIN Range 10: Begin:	2C4RC1FGXRR191423	End:	2C4RC1FGXRR191423	☐ Not sequential

Part 573 Safety Recall Report	24V-888	Page 5
The information contained in this report was submitted	d pursuant to 49 CFR §573	

Vahiala 2 . 2024	2024 Chryslan Variager ar	nd Danie	fica	
Vehicle 3: 2024-	2024 Chrysler Voyager ar	iu Pacii	nca	
Body Style :				
Power Train: NR				
	0/2024 discovered some	. coota i	in contain convented WAVs	did not have the
	rs installed. \cdot Determined		found 34 Voyager, and 10	
Production Dates: OCT 2				
VIN Range 1 : Begin :	2C4RC1BG1NR188197	End:	2C4RC1BG1NR188197	✓ Not sequentia
VIN Range 2 : Begin :		End:		☐ Not sequentia
VIN Range 3 : Begin :		End:	2C4RC1BG4NR190493	☐ Not sequentia
VIN Range 4 : Begin :		End:		☐ Not sequentia
VIN Range 5 : Begin :		End:		☐ Not sequentia
VIN Range 6 : Begin :		End:		Not sequentia
VIN Range 7 : Begin :		End:		Not sequentia
VIN Range 8: Begin:	2C4RC1CG0PR603012	End:		Not sequentia
VIN Range 9 : Begin :	2C4RC1CG1PR587869	End:		Not sequentia
VIN Range 10: Begin:		End:		☐ Not sequentia
VIN Range 11 : Begin :		End:		☐ Not sequentia
VIN Range 12 : Begin :	2C4RC1CG4PR598042	End:	2C4RC1CG4PR598042	☐ Not sequentia
VIN Range 13: Begin:	2C4RC1BG5RR180626	End:	2C4RC1BG5RR180626	☐ Not sequentia
VIN Range 14: Begin:	2C4RC1FG2RR191383	End:	2C4RC1FG2RR191383	☐ Not sequentia
VIN Range 15: Begin:	2C4RC1FG4RR191384	End:	2C4RC1FG4RR191384	☐ Not sequentia
VIN Range 16: Begin:		End:	2C4RC1FG6RR183240	☐ Not sequentia
VIN Range 17: Begin:	2C4RC1FG4RR195869	End:	2C4RC1FG4RR195869	☐ Not sequentia
VIN Range 18: Begin:		End:	2C4RC1FGXRR191423	☐ Not sequentia
VIN Range 19: Begin:	2C4RC1CG0RR140906	End:	2C4RC1CG0RR140906	☐ Not sequentia
VIN Range 20 : Begin :	2C4RC1CG1RR169959	End:		☐ Not sequentia
VIN Range 21 : Begin :	2C4RC1CG2RR152636		2C4RC1CG2RR152636	☐ Not sequentia
VIN Range 22 : Begin :	2C4RC1CG2RR152670		2C4RC1CG2RR152670	☐ Not sequentia
VIN Range 23 : Begin :	2C4RC1CG3RR157943	End:	2C4RC1CG3RR157943	☐ Not sequentia
VIN Range 24 : Begin :		End:		Not sequentia
VIN Range 25 : Begin :	2C4RC1CG6RR130090	End:	2C4RC1CG6RR130090	Not sequentia
VIN Range 26 : Begin :	2C4RC1CG6RR140893	End:		Not sequentia
VIN Range 27 : Begin :	2C4RC1CG6RR141168	End:		Not sequentia
VIN Range 28 : Begin :	2C4RC1CG6RR141171	End:		Not sequentia
VIN Range 29 : Begin :	2C4RC1CG6RR141199		2C4RC1CG6RR141199	Not sequentia
VIN Range 30 : Begin :	2C4RC1CG7RR141213		2C4RC1CG7RR141213	☐ Not sequentia
VIN Range 31 : Begin :	2C4RC1CG7RR152518	End:		Not sequentia
VIN Range 32 : Begin :	2C4RC1CG7RR152647		2C4RC1CG7RR152647	Not sequentia
VIN Range 33 : Begin :	2C4RC1CG8RR130107	End:		Not sequentia
VIN Range 34 : Begin :	2C4RC1CG8RR130110	End:		Not sequentia
VIN Range 35 : Begin :	2C4RC1CG8RR140894	End:		☐ Not sequentia
VIN Range 36 : Begin :	2C4RC1CG8RR141169	End:		☐ Not sequentia
VIN Range 37 : Begin :	2C4RC1CG8RR141172		2C4RC1CG8RR141172	Not sequentia
VIN Range 38 : Begin :	2C4RC1CG8RR155718	End:	2C4RC1CG8RR155718	Not sequentia

Description of Noncompliance:

Description of the FMVSS 208 - Missing seat limiter effecting occupant crash protection

Noncompliance: compliance

The seat limiter ensures proper occupant positioning in the event of a crash or

air bag deployment.

FMVSS 1: 208 - Occupant crash protection

FMVSS 2: NR

Description of the Safety Risk: Absence of a seat limiter could result in greater risk of injury to the occupant

in the event of a collision.

Description of the Cause: Seat limiter, which is installed to limit forward motion of the seat, was

potentially omitted during the manufacturing process

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: Seat Limiter

Component Description: BRKT - TRAVEL STOP

Component Part Number: 510116BK

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

11/19/2024, during random quality audits we discovered some seats in certain converted WAVs did not have the seat limiters installed \cdot Determined scope of potentially affected units. \cdot Met with level 1 group 11/20/2024 44 units were found to be potentially affected. Final decision of non compliance determined 11-21-2024.

Description of Remedy:

Description of Remedy Program: Inspect and add limiter if found missing, BraunAbility will reimburse

dealers for parts and labor.

How Remedy Component Differs The inspection will indicate how to distinguish if the part is missing from

from Recalled Component: the seat.

Identify How/When Recall Condition During random quality audits (11-19-2024) we discovered some seats in was Corrected in Production: certain converted WAVs did not have the seat limiters installed. We

implemented continuous inspection of the seat limiter on 11-19-2024 to

verify continuous compliance in production.

Recall Schedule:

Description of Recall Schedule: Planning dealer notifications on 12-2, customer notifications to start

12-16

Planned Dealer Notification Date : DEC 02, 2024 - DEC 06, 2024 Planned Owner Notification Date : DEC 16, 2024 - DEC 23, 2024

^{*} NR - Not Reported