OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24V-966

Manufacturer Name: Storyteller Overland

Submission Date: DEC 23, 2024 **NHTSA Recall No.:** 24V-966

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Storyteller Overland

Address: 428 Industrial Lane

BIRMINGHAM AL 35211

Company phone: 9997442

Population:

Number of potentially involved: 80 Estimated percentage with defect: NR

Vehicle Alterer Information:

Vehicle 1: 2024-2024 Storyteller Overland Beast Mode, Classic Mode, Stealth Mode, Mystic

Mode

Descriptive Information: The recall population was determined by our supplier, Lithionics Battery LLC,

based on the analysis of two alternators that were determined to be from the

same manufacturing batch.

Production Dates: JUN 27, 2023 - AUG 29, 2024

Description of Defect:

Description of the Defect: The vehicle's secondary alternator may contain a manufacturing defect which

could cause an electrical short inside the alternator.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Due to the potential defect, the alternator could overheat creating the risk of

fire.

Description of the Cause: An internal component of the alternator may be improperly torqued.

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name: 48V BSG Alternator Large Format

Component Description : Alternator
Component Part Number : 85-300-4850

Supplier Identification:

Component Manufacturer

Name: Lithionics Battery LLC

Address: 1770 Calumet St

Clearwater Florida 33765

Country: United States

Chronology:

On August 4th, 2024, a customer reported an alternator thermal event. Storyteller's Service Team coordinated with Storyteller's battery system supplier, Lithionics Battery, to analyze the alternator, and Storyteller's Safety Committee opened an investigation. Representatives of Lithionics Battery identified a manufacturing error internal to the alternator relating to a suspected improperly torqued screw.

On November 14th, 2024, a customer reported a potential battery system thermal event.

On November 22nd, 2024, a dealer reported an alternator not charging. The dealer's service team identified potential heat markers on the alternator, and the alternator was sent to Lithionics Battery for evaluation.

Representatives of Storyteller and Lithionics met on December 20th, 2024 to review production data from Lithionic Battery's sub-supplier. Both field alternators that were reviewed by Lithionics representatives were identified as stemming from a single production batch from Lithionics' sub-supplier. Storyteller's Safety Committee met immediately after the meeting with Lithionics and voted to recall the suspect population.

Description of Remedy:

Description of Remedy Program : Alternators will be replaced at no cost to the customer at an authorized

Storyteller dealer. If you have already paid for these repairs, please contact Storyteller at warranty@storytelleroverland.com with the details of the repair including pictures of the completed repair and remedied part as

well as a labor sheet or invoice. Once we have received proof of satisfactory completion and your invoice, we will coordinate

reimbursement. There are no time frame or eligibility restrictions to get

reimbursed for this repair.

How Remedy Component Differs Replacement alternators will not be from the suspect population identified

from Recalled Component: by Storyteller's supplier.

Identify How/When Recall Condition Storyteller reviewed production data to ensure no alternator inventory on

was Corrected in Production: hand was from the suspect population.

Recall Schedule:

Description of Recall Schedule: Dealer and owner notification letters will be sent within the 60-day

requirement.

Planned Dealer Notification Date : FEB 20, 2025 - FEB 21, 2025 Planned Owner Notification Date : FEB 20, 2025 - FEB 21, 2025

Purchaser Information:

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name:

Address:

Country:

Company Phone:

* NR - Not Reported