OMB Control No.: 2127-0004

Part 573 Safety Recall Report

25V-061

Manufacturer Name: Grand Design RV, LLC

Submission Date: FEB 06, 2025 NHTSA Recall No.: 25V-061 Manufacturer Recall No.: 910048



Manufacturer Information:

Manufacturer Name: Grand Design RV, LLC

Address: 11333 County Road 2

Middlebury IN 46540

Company phone: (574) 825-8000 x2015

Population:

Number of potentially involved: 21,982 Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2019-2024 Grand Design Solitude

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information : The basis for determining the recall population was established by purchase order

information of the step treads in question. The recall products differ from current products in material composition, dimension and assembly. The number of affected

products related to this specific make/model year combination is 21,982.

Production Dates: JUN 01, 2018 - AUG 16, 2023

Vehicle 2: 2019-2024 Grand Design Solitude

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: The basis for determining the recall population was established by purchase order

information of the step treads in question. The recall products differ from current products in material composition, dimension and assembly. The number of affected

products related to this specific make/model year combination is 21,982.

Production Dates: JUN 01, 2018 - AUG 16, 2023

 VIN Range 1 : Begin :
 573FS3627K1112427
 End :
 573FS3628K1112436
 ✓ Not sequential

 VIN Range 2 : Begin :
 573FS3620K9900001
 End :
 573FS4222L9907142
 ☐ Not sequential

 VIN Range 3 : Begin :
 573FS4327LAA00001
 End :
 573FS4222RAA16665
 ☐ Not sequential

Description of Defect:

Description of the Defect: The defect is an interior laminated step that can break at the laminated joints.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The step tread can break, while in use, increasing the risk of fall and injury.

Description of the Cause: The step treads are laminated hardwood. If the laminated joint aligns with the

step riser, the joint of the step tread may be unsupported. This can result in the

step tread breaking.

Identification of Any Warning There may be some noticeable separation at the lamination joint on the step

that can Occur: tread, prior to failure. Due to the nature of the texture on the step tread, there

is not always a noticeable warning.

Involved Components:

Component Name 1: Step Tread

Component Description: 11 3/4 X 26 15/16 OAK BLACK FINISH 1H-125

Component Part Number: 692792

Supplier Identification:

Component Manufacturer

Name: MJ Finishing, LLC

Address: 5311 East County Line Road Bremen IN 465

Bremen 46506

Country: NR

Chronology:

3/11/24 - Grand Design issued a Technical Service Bulletin via our Grand Design dealer portal to address complaints in the field, for interior steps that broke at the laminated joint. 12/4/24 GD Customer service was notified of a broken step that had resulted in a minor injury.

Description of Remedy:

Description of Remedy Program: The remedy program is currently under development. Repairs made prior

to the recall will be reimbursed in accordance with our recall

reimbursement plan.

How Remedy Component Differs Remedy components are distinguished from the recalled component

from Recalled Component: because they are a composite material. Recalled components are

laminated hardwood.

Identify How/When Recall Condition Production has updated to the remedy composite tread. Changes were

was Corrected in Production: implemented August 2023.

Recall Schedule:

Description of Recall Schedule: Dealer notification letters are expected to be mailed March 20, 2025.

Planned Dealer Notification Date : MAR 20, 2025 - MAR 20, 2025 Planned Owner Notification Date : MAY 01, 2025 - MAY 01, 2025

* NR - Not Reported